



**171 TAYLOR
STREET,
CAMBRIDGE**

**PRELIMINARY
GEOTECHNICAL
ASSESSMENT**

PROJECT NO: HD1934
KOTARE CONSULTANTS
REFERENCE: PCR
09 APRIL 2021

Executive summary

Introduction

Errol Hall has engaged us to undertake a preliminary geotechnical assessment for the site located at 171 Taylor Street, Cambridge. They propose to subdivide the site to create 1 additional lot. This report is intended to be submitted to the Waipa District Council in support of the subdivision consent application.

Our scope included

- a desktop study of the site to review existing information, including historical aerial images, geology maps, contour maps, and the NZ Geotechnical Database (NZGD)
- a hand auger investigation, including 1 hand auger with strength testing and 2 soakage tests
- a natural hazards assessment, including a qualitative liquefaction assessment
- preliminary stormwater recommendations
- preliminary foundation recommendations


Our key findings were

- ground conditions were consistent with the mapped Hinuera Formation
- the degree of liquefaction induced ground damage is likely to be 'none to minor'
- disposal of stormwater via soakage is not viable for the proposed lot and we recommend a detention type system
- the strength requirements for 'good ground' in accordance with NZS3604:2011 are not achieved due to low strength soils encountered
- deepened foundations are suitable for a suspended timber floor structure
- standard foundations (according to NZS3604:2011) with ground improvements to approx. 1.3 m below ground level or a raft type foundation designed for low bearing capacity are suitable for a concrete floor building

Contents

Executive summary	i
Introduction	i
Our scope included	i
Our key findings were	i
Introduction	1
Scope.....	1
Site description	1
Desk study.....	1
Geological setting.....	1
Aerial photography	1
NZGD	2
Site investigation.....	2
Ground conditions	2
Groundwater.....	2
Geotechnical assessment.....	2
Natural hazards	2
Liquefaction	2
Preliminary stormwater assessment	3
Preliminary foundation recommendations	3
Summary	4
Limitation	4
Appendix A – Subdivision scheme	A
Appendix B – Site investigation results.....	B
Appendix C – HCC liquefaction outputs	C

PREPARED BY: **Brad Kroef**



GRADUATE
GEOTECHNICAL ENGINEER
Brad@hdgeo.co.nz
Tel 027 223 5441

REVIEWED BY **Andrew Holland, CPEng**



TECHNICAL DIRECTOR, PRINCIPAL
ENGINEER
Andrew@hdgeo.co.nz
Tel 022 048 8441

Introduction

Errol Hall proposes to subdivide the property located at 171 Taylor Street, Cambridge to create 1 new lot. We have been engaged to undertake a preliminary geotechnical assessment for the new lot. This report presents the results of our investigation and assessment for the proposed lot (Lot 2). A site plan showing the subdivision scheme is included in Appendix A.

This report is intended to be submitted to the Waipa District Council in support of an application for subdivision consent. Further testing and assessment will be needed at building consent stage.

Scope

The scope of our assessment included a:

- desktop study of the site to review existing information, including historical aerial images, geology maps, contour maps, and the NZ Geotechnical Database (NZGD)
- hand auger investigation, including 1 hand auger with strength testing and 2 soakage tests
- natural hazards assessment, including a qualitative liquefaction assessment
- preliminary stormwater recommendations
- preliminary foundation recommendations

Site description

The site is located at 171 Taylor Street, Cambridge. It is bounded by Taylor Street to the north and residential houses to all other boundaries. The site is flat and approximately 68 m above local datum. An existing dwelling is located on the northern side of the property within the proposed Lot 1 and a shed which is to be removed on the southern side within the proposed Lot 2. There is a gully and stream system located approximately 650 m to the south at approximately 22 m above local datum¹.

Desk study

Geological setting

The geology map of the area² indicates that the site is underlain by the Hinuera Formation, which is described as cross-bedded pumice sand, silt and gravel with interbedded peat.

Aerial photography

We have sourced historic photos of the site from Retrolens³ and Google Earth⁴. Clear photos were available from 1939. The photos show that no significant changes were present until between 1953 and 1967 when the existing house on the property was built. No significant changes were seen on the site after 1967.

¹ Waikato Regional Council Contours, Local Maps, <https://waikatomaps.waikatoregion.govt.nz/Viewer/?map=8d6d6fda779b4e59951953ae97d0ec4a>, Accessed 23/03/2021.

² 1:250,000 Geological Map of New Zealand. New Zealand Geology Web Map. GNS, 2013. <http://data.gns.cri.nz/>. Accessed 23/03/2021.

³ <http://retrolens.nz/>

⁴ Google Earth Pro

NZGD

We have reviewed the NZ Geotechnical Database (NZGD) in the area of the site. The database has 2 sites within 200m with 8 hand augers in total. Ground conditions on these sites confirmed the geology mapped and encountered.

Site investigation

Our site investigation included a site walkover, 1 hand augers and 2 soakage tests. Soil logs and site plan can be seen in Appendix B.

Ground conditions

The materials we encountered on site were consistent with the mapped Hinuera Formation. Ground conditions on site consisted of:

- topsoil to 0.3 m below ground level (bgl)
- stiff clay with some silt to 0.7 m bgl
- loose silty sand to 0.9 m bgl
- stiff silty clay to 1.2 m bgl
- medium dense to dense sand to 3.0 m bgl

Groundwater

Groundwater was not encountered during this investigation up to a depth of 3.0 m bgl. Groundwater is expected to be at a depth greater than 4 m bgl.

Geotechnical assessment

Natural hazards

- Earthquake: The site subsoil class is D 'Deep or soft soils'. For Earthquake induced liquefaction see liquefaction section below.
- Tsunami, volcanic, geothermal, or sedimentation activity: The site is not near any known sources of these risks.
- Landslips: The site is level with no anticipated instability
- Erosion: No indications of erosion were observed during the site investigation and we consider the site to be at low risk of damage due to erosion.
- Subsidence: Risk of the site to general subsidence is low.

Liquefaction

We have undertaken a qualitative liquefaction assessment for the site using the latest guidelines. This assessment qualifies as a Level B (calibrated desk study) in accordance with the 2017 planning guidelines⁵. Class D soils have been assumed for this assessment.

A desktop study, conducted by Tonkin and Taylor⁶, was carried out for the Hamilton City Council to help define the liquefaction risk within Hamilton City. The site is in the same geology as the HCC desk study. The sites 1/500 year event peak ground acceleration was calculated to be 0.25g⁷. The 1/1000

⁵ Earthquake Commission (EQC) / Ministry for the Environment and Ministry of Business, Innovation and Employment. 'Planning and engineering guidance for potentially liquefaction prone land' Rev 01. Dated September 2017.

⁶ 'Liquefaction Desktop Study' prepared by Tonkin & Taylor for Hamilton City Council, Ref No. 1007144.v1.1, dated February 2019

⁷ New Zealand Transport Agency (October 2018). Bridge Manual (SP/M/022). Third edition, Amendment 3

year peak ground acceleration used in the HCC desk study is 0.28g. The HCC desk study 1/1000 year event can be used for a conservative assessment. The HCC outputs used can be seen in Appendix C.

As discussed above, the groundwater at the site is expected to be at depths greater than 4 m bgl. Using the 1/1000 year analysis in the desk study, for an expected groundwater of 4m, the degree of liquefaction induced ground damage is likely to be none to minor.

As the liquefaction effects are likely to be none to minor, no further consideration of liquefaction is needed.

Preliminary stormwater assessment

We undertook a falling head permeability test in general accordance with NZBC Verification Method E1/VM4⁸ to determine the soakage capacity of the soils within the site. Tests were undertaken on the northern end of the access area and the south western corner of Lot 2.

Typical ground conditions within the soakage tests consisted of topsoil underlain by silts and sands consistent with the Hinuera Formation.

We determined percolation rates to be the following and can be seen in Appendix B:

Soakage test	Depth of test (m bgl)	Soakage rate (mm/hr)	Design soakage rate (mm/hr)*
ST01	2.0	268	133
ST02	2.0	182	90

* a 50% reduction rate has been applied as per the RITS⁹

The design soakage rates shown are below the minimum soakage threshold of 150 mm/hr specified in the RITS. Based on the soakage rate and soils encountered we consider disposal of stormwater via soakage not viable for the proposed lot. We recommend a detention type system with a slow release to the kerb.

Preliminary foundation recommendations

The strength requirements of 'good ground' according to NZS 3604:2011 were not met below the topsoil across the site up to a depth of 1.3 m. For a suspended timber floor building we expect standard NZS3604:2011 foundations deepened to at least 1.3 m bgl to be suitable. For a concrete floor building we expect standard NZS3604:2011 foundations with ground improvements or a raft type foundation designed for a reduced bearing capacity to be suitable.

Ground improvements would include excavation to remove topsoil and any soft, loose or unsuitable material. Any excavation would be replaced with compacted hardfill. Our preliminary testing indicates excavation depth would be to approximately 1.3 m.

⁸ Ministry of Business, Innovation & Employment, 'Acceptable Solutions and Verification Methods, For New Zealand Building Code Clause, E1 Surface Water', 1st Edition Amendment 10, dated 1 January 2017

⁹ 'Regional Infrastructure Technical Specification' v1.0, Waikato Local Authority Shared Services, dated May 2018

Summary

- ground conditions were consistent with the mapped Hinuera Formation
- the degree of liquefaction induced ground damage is likely to be 'none to minor'
- disposal of stormwater via soakage is not viable for the proposed lot and we recommend a detention type system
- the strength requirements for 'good ground' in accordance with NZS3604:2011 are not achieved due to low strength soils encountered
- deepened foundations are suitable for a suspended timber floor structure
- standard foundation (according to NZS3604:2011) with ground improvements or a raft type foundation designed for low bearing capacity are suitable for a concrete floor building

Further investigation, assessment and design will be required at building consent stage.

Limitation

This report has been prepared for our client, Errol Hall, their professional advisers and the relevant local authority for the purposes detailed above and may not be relied on by any other party for any other purposes. This report contains a preliminary assessment to establish suitability for subdivision based on a site walkover and testing in discrete locations. Inferences about the conditions at the site have been made based on the testing undertaken and our understanding of the geological environment in which the site lies. We recommend that a suitably qualified engineer is engaged to undertake further testing and assessment for building consent, and to observe works during the site preparation.

APPENDIX A – SUBDIVISION SCHEME

MEMORANDUM OF EASEMENTS (Pursuant to s243 Resource Management Act 1991)			
Purpose /Interest	SHOWN	Burdened Land (Servient Tenement)	Benefited Land (Dominant Tenement)
RIGHT TO DRAIN SEWAGE	Ⓐ	LOT 2 HEREON	LOT 1 HEREON
	Ⓑ	LOT 2 DPS 5001	LOTS 1 & 2 HEREON



PROPERTY DETAILS:
LEGAL DESCRIPTION:
LOT 4 DEEDS 605
— AREA: 0.1012 Ha
— COMPRISED IN SA1404/6 (Ltd.)
— WAIPA DISTRICT COUNCIL
— ZONING: RESIDENTIAL
COMPACT HOUSING OVERLAY

- NOTES:
1. HEIGHTS ARE IN TERMS OF MOTURIKI VERTICAL DATUM 1953 WHERE APPLICABLE
 2. DATUM MARK TBC
 3. CONTOUR INTERVAL N/A
 4. AREAS AND DIMENSIONS SHOWN ARE SUBJECT TO FINAL SURVEY.



KOTARECONSULTANTS

Shop 4
Victoria Arcade
75 Victoria Street
Cambridge 3434 NZ

Tel: 07 827 5340
www.kotareconsultants.co.nz
ciaran@kotareconsultants.co.nz



SUBDIVISION CONCEPT PLAN
Lots 1 and 2 Being a Subdivision of LOT 4 DEEDS 605
AT 171 TAYLOR STREET, CAMBRIDGE 3434
ERROL MURRAY HALL

REVISION	Rev0	Original	2 NOV 2020	JOB	SHEET
				1014	00
DATE	NOVEMBER 2020	ORIGINAL SCALE AT A3		REV 0	
CAD	CPM	1:250			

APPENDIX B – SITE INVESTIGATION RESULTS



LEGEND

- Hand auger 
- Site boundary 

PROJECT: 171 Taylor Street, Cambridge

PROJECT No: HD1938

CLIENT: Errol Hall

TITLE: Site plan

SCALE: N/A

Drawing No: 01

Drawing By: BK



Rev no:












1	Initial



Notes:
1. Image sourced from Google Earth Pro



20 m

		INVESTIGATION LOG					Job No.: HD1938	
		Client: Errol Hall					No.: HA01	
		Project: 171 Taylor St, Cambridge					Date: 26.03.21	
		Location: Northwestern corner of Lot 2.					Logged By: AM	
Co-ordinates: 1817917mE, 5804569mN					Checked By: BS			
Elevation: Ground								
Geology	Geological Interpretation (refer to separate Geotechnical and Geological Information sheet for further information)	Depth (m)	Legend	Scala Penetrometer (Blows / 100 mm)	Vane Shear Strength (kPa) Vane: 2108		Water	
Topsoil	TOPSOIL; dark brown. Dry; rootlets.	0.2	[Pattern]	5				
				3				
Loam	CLAY, with some silt; yellowish brown. Stiff; dry; moderate plasticity.	0.4	[Pattern]	4			160	
				4				
				7				
				5				
Hinuera Formation	Silty SAND; light greyish yellow. Loose; dry; low dilatancy; uniformly graded; sand, fine.	0.8	[Pattern]	3			197	
				2				
	Silty CLAY, with some sand; white with minor orange mottles. Stiff to very stiff; dry; moderate plasticity; sand, fine.	1.0	[Pattern]	3			196	
				3				
				3				
	SAND, with minor gravel; greyish brown. Medium dense to dense; moist; well graded; sand, coarse; gravel, fine. 1.2 m - 1.3 m: Changes to Silty SAND; brownish orange.	1.2	[Pattern]	3			175	
				3				
				6				
				7				
				5				
				8				
				7				
				5				
				7				
				8				
				10				
				12				
				10				
11								
9								
8								
9								
11								
8								
EOH: 3.00 m	3.0	[Pattern]	8					
Photo		Remarks						
		End of log at 3.0 m - target depth. <div> <div> Shear Vanes <div> <div>Peak</div> <div>Remoulded</div> </div> </div> <div> Water <div> <div>Standing Water Level</div> <div>Out flow</div> <div>In flow</div> </div> </div> <div> Investigation Type <div> <div><input checked="" type="checkbox"/> Hand Auger</div> <div><input type="checkbox"/> Investigation Pit</div> <div><input type="checkbox"/> Machine Borehole</div> </div> </div> </div>						

		INVESTIGATION LOG						Job No.: HD1938										
		Client: Errol Hall						No.: ST01										
		Project: 171 Taylor St, Cambridge						Date: 26.03.21										
		Location: Northern end of access are of Lot 2.						Logged By: AM										
Co-ordinates: 1817934mE, 5804587mN						Checked By: BS												
Elevation: Ground																		
Geology	Geological Interpretation (refer to separate Geotechnical and Geological Information sheet for further information)	Depth (m)	Legend	Scala Penetrometer (Blows / 100 mm)						Vane Shear Strength (kPa) Vane:	Water							
				2	4	6	8	10	12	14	16	18	50	100	150	200	250	
Topsoil	TOPSOIL; brown; bedded. Rootlets.	0.2																Groundwater Not Encountered
		0.4																
Loam	Sandy SILT; light yellowish brown. Medium dense; dry; moderate dilatancy; sand, fine.	0.6																
		0.8																
		1.0																
Hinuera Formation	SAND; dark yellowish brown. Medium dense to dense; moist; well graded; sand, coarse.	1.2																
		1.4																
		1.6																
		1.8																
	Silty SAND, with minor clay, with trace gravel; light grey. Dense; moist; well graded; sand, coarse; gravel, fine.	2.0																
	EOH: 2.00 m																	
Photo			Remarks															
			End of log at 2.0 m - target depth. <div> <div> Shear Vanes <div>  Peak  Remoulded </div> </div> <div> Water <div>  Standing Water Level  Out flow  In flow </div> </div> <div> Investigation Type <div> <input type="checkbox"/> Hand Auger <input type="checkbox"/> Investigation Pit <input checked="" type="checkbox"/> Machine Borehole </div> </div> </div>															

	INVESTIGATION LOG						Job No.: HD1938											
	Client: Errol Hall						No.: ST02											
	Project: 171 Taylor St, Cambridge						Date: 26.03.21											
	Location: Southeastern corner of Lot 2.						Logged By: AM											
Co-ordinates: 1817935mE, 5804559mN						Checked By: BS												
Elevation: Ground																		
Geology	Geological Interpretation (refer to separate Geotechnical and Geological Information sheet for further information)	Depth (m)	Legend	Scala Penetrometer (Blows / 100 mm)				Vane Shear Strength (kPa) Vane:				Water						
				2	4	6	8	10	12	14	16	18	50	100	150	200	250	
Topsail	TOPSOIL; dark brown. Rootlets.	0.2	TS															Groundwater Not Encountered
Loam	SILT, with some sand, with minor clay; brownish orange. Medium dense; dry; low dilatency.	0.4	X															
Hinuera Formation	Sandy SILT, with some clay; light greyish yellow. Medium dense to dense; dry; moderate plasticity.	0.6																
		0.8																
		1.0																
		1.2																
		1.4																
	SAND, with trace gravel; light greyish brown. Dense; moist; well graded; sand, coarse; gravel, fine.	1.6																
		1.8																
	EOH: 2.00 m	2.0																
Photo			Remarks															
			End of log at 2.0 m - target depth.															
			<div><div>Shear Vanes<div><div></div>Peak<div></div>Remoulded</div></div><div>Water<div><div></div>Standing Water Level<div></div>Out flow<div></div>In flow</div></div><div>Investigation Type<div><div></div>Hand Auger<div></div>Investigation Pit<div><input checked="" type="checkbox"/></div>Machine Borehole</div></div></div>															



Job name	171 Taylor Street
Job number	HD1938
Date	31/03/2021
Plotted by	BK
Reviewed by	BS


Perc test results

ST01

Calculated in general accordance with E1/VM1 - Surface Water, Section 9.0

Hole depth: 2.000 m
Ground water depth: None m

Notes:



Percolation rate calculation:

Time (Hour)	Drop (mm)	
2.00	1683	Minimum slope (lower)
2.40	1790	Minimum slope (upper)

Percolation rate = 268 mm/hr
50% Percolation rate = 133 mm/hr



Job name	171 Taylor Street
Job number	HD1938
Date	31/03/2021
Plotted by	BK
Reviewed by	BS


Perc test results

ST02

Calculated in general accordance with E1/VM1 - Surface Water, Section 9.0

Hole depth: 2.000 m
Ground water depth: None m

Notes:



Percolation rate calculation:

Time (Hour)	Drop (mm)	
2.00	1634	Minimum slope (lower)
2.60	1743	Minimum slope (upper)

Percolation rate = 182 mm/hr
50% Percolation rate = 90 mm/hr


APPENDIX C – HCC LIQUEFACTION OUTPUTS

Figure C2.14


CPT based liquefaction analysis

Scenario: 1000 yr ARI (Mw=5.9,PGA = 0.28g) 4m GWD

Histograms of LSN values by geomorphic group



Box and whisker plot of LSN values by geomorphic group




Legend

Degree of liquefaction induced ground damage	Characteristic LSN values ($P_L=15\%$)
None to Minor	0-13
Minor to Moderate	13-18
Moderate to Severe	>18

These values are intended only for use in area-wide hazard assessment using the MBIE (2017) performance criteria. Different values may be more appropriate for other purposes (such as site-specific design).

Notes

1. Refer to Table 2.2 and Appendix A of the MBIE liquefaction guidance document for further information about land damage categories.
2. Liquefaction analyses are undertaken assuming a probability of liquefaction (P_L) of 15%. (Refer to section 4.2 for further detail)
3. Box and Whisker plot key:



APPENDIX D

CCTV REPORT



"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACCUUM LOADING AND SEPTIC TANKS

f facebook.com/AssassinDrainageSolutions assassin.co.nz PH:0800 938 538

Documentation For CCTV-inspection

Contractor **Assassin Drainage Solutions Ltd**

Client **Kotare Consultants**

Contract No.

Project **171 Taylor Street**

Standard **New Zealand Pipe Inspection
created with can3D®**

Comments:

Disclaimer: Assassin Water Jetters Ltd accepts no liability for peg markings or any other markings once Assassin have left the property/site.

The Attached Photos/CCTV MAP is a reference only and should in no circumstances be used as a site plan for further work

If piling within 3m of pipes a Manual visual inspection is required to verify pipe location



"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACCUM LOADING AND SEPTIC TANKS


f facebook.com/AssassinDrainageSolutions assassin.co.nz PH:0800 938 538

Measurements report

Operator Aaron
Client Kotare Consultants

Contract No.
Contractor Assassin Drainage Solutions Ltd

	Total	Insp. m
Length of all pipes	0.00	24.80
Sum of all images	14	

No.	Upper point	Lower point	Date	Street	Material/Dia	Kind of water	m	Insp....	
1	171 Taylor St...	1332648	26/02/20...	171 Taylor Street	EW /100	Foul/sanitary se...		24.8	14
EW - 100/100							0	24.8	14



"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACUUM LOADING AND SEPTIC TANKS

f facebook.com/AssassinDrainageSolutions assassin.co.nz PH:0800 938 538

Pipe Summary Report

New Zealand Pipe Inspection			Operator	Inspection Completion	Time Started	Date Started
Client				Inspection Complete	4:07 PM	26/02/2021
Kotare Consultants			Camera Operator	Currency of Inspection	Comments	
Contract No.			Aaron			
Drawing No.			Weather	Status of Pipe		
Inspection No. 1			Dry Weather	Original Condition		
Asset No.	171 Taylor Street	Set-up	upstream	Shape	Circular Pipe	
Upper Node	171 Taylor Street	Line Length (m)		Material	Earthenware	
Lower Node	1332648	Surveyed Length (m)	24.8	Use	Foul/sanitary sewer	
Surface	Mown Lawn	Location	Private Property - Yard	Pipeline Height (Diameter in mm)	100	
Grading			Structural	Mean	Structural Peak	Structural Total
5			4.1	50.0	101.0	
Grading Service			Service Peak	Service Mean	Service Total	
3			10.0	1.0	25.0	

171 Taylor Street						
0.00m (25.49m)	IS	00:05	Inspection Start			
1.63m (23.86m)	2 JFL	00:17	Joint, Faulty, Large, 3-11 o'clock, Joint has root intrusion .			
1.63m (23.86m)	5 RIS	00:17	Root Intrusion, Small, 8-3 o'clock			
2.31m (23.18m)	1 JFS	00:21	Joint, Faulty, Small, 8-3 o'clock, Joint has root intrusion .			
2.31m (23.18m)	5 RIS	00:21	Root Intrusion, Small, 8-3 o'clock			
2.86m (22.63m)	2 JFL	00:27	Joint, Faulty, Large, 12-12 o'clock, Circumferential crack in joint zone and root intrusions.			
2.86m (22.63m)	5 RIS	00:27	Root Intrusion, Small, 12-12 o'clock			
3.50m (21.99m)	2 JFL	00:31	Joint, Faulty, Large, 9-3 o'clock, Joint has root intrusion .			
3.50m (21.99m)	5 RIS	00:32	Root Intrusion, Small, 9-3 o'clock			
5.49m (20.00m)	2 JFL	00:42	Joint, Faulty, Large, 9-3 o'clock, Joint has root intrusion .			
5.49m (20.00m)	5 RIS	00:42	Root Intrusion, Small, 9-3 o'clock			
6.59m (18.90m)	MC	00:49	Material Change, EW TO PVC			
6.59m (18.90m)	0 JDS	00:50	Joint, Displaced, Small, Jointing method has moved .			
6.81m (18.68m)	LR	00:54	Line Deviates, Right			
7.98m (17.51m)	LL	00:59	Line Deviates, Left			
8.24m (17.25m)	MC	01:06	Material Change, PVC TO EW			
8.24m (17.25m)	0 JDS	01:06	Joint, Displaced, Small			
23.77m (1.72m)	CF	02:41	Construction Feature, 11-1 o'clock Inspection Lid.			
24.91m (0.58m)	LD	02:49	Line Deviates, Down			
25.49m (0.00m)	IE	02:56	Inspection Ends, Connection to Main .			

1332648



"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACUUM LOADING AND SEPTIC TANKS



facebook.com/AssassinDrainageSolutions

assassin.co.nz

PH:0800 938 538

Image report pipe

Contract No.

Parallel Line

Time Started

4:07 PM

Date Started

26/02/2021

Asset No. 171 Taylor Street
Upper Node 171 Taylor Street
Lower Node 1332648
Pipeline Height (Diameter in...) 100
Pipeline Width (mm)

Line Length (m)

Material

Earthenware

Shape

Circular Pipe

Joint Spacing

Operator

Surveyed Length (m) 24.8

Camera Operator Aaron

Currency of Inspection Current Inspection

Set-up upstream

Inspection Completion Inspection Complete

Inspection No. 1

Inspection Start

Position 0.00m

Code abbreviations IS

Damage category



Joint, Faulty, Large, 3-11 o'clock, Joint has root intrusion .

Position 1.63m

Code abbreviations JFL

Damage category

25





"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACCUM LOADING AND SEPTIC TANKS

f facebook.com/AssassinDrainageSolutions assassin.co.nz PH:0800 938 538

Image report pipe

Contract No.

Parallel Line

Asset No. 171 Taylor Street
Upper Node 171 Taylor Street
Lower Node 1332648
Pipeline Height (Diameter in...) 100
Pipeline Width (mm)

Line Length (m)

Material

Earthenware

Shape

Circular Pipe

Joint Spacing

Joint, Faulty, Small, 8-3 o'clock, Joint has root intrusion .

Position 2.31m

Code abbreviations JFS

Damage category 1



Joint, Faulty, Large, 12-12 o'clock, Circumferential crack in joint zone and root intrusions.

Position 2.86m

Code abbreviations JFL

Damage category 25





"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACUUM LOADING AND SEPTIC TANKS

f facebook.com/AssassinDrainageSolutions assassin.co.nz PH:0800 938 538

Contract No.

Image report pipe

Asset No. 171 Taylor Street
Upper Node 171 Taylor Street
Lower Node 1332648
Pipeline Height (Diameter in...) 100
Pipeline Width (mm)

Parallel Line

Line Length (m)

Material

Earthenware

Shape

Circular Pipe

Joint Spacing

Joint, Faulty, Large, 9-3 o'clock, Joint has root intrusion .

Position 3.50m

Code abbreviations JFL

Damage category 25



Joint, Faulty, Large, 9-3 o'clock, Joint has root intrusion .

Position 5.49m

Code abbreviations JFL

Damage category 25





"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACUUM LOADING AND SEPTIC TANKS

f facebook.com/AssassinDrainageSolutions assassin.co.nz PH:0800 938 538

Contract No.

Image report pipe

Parallel Line

Asset No. 171 Taylor Street
Upper Node 171 Taylor Street
Lower Node 1332648
Pipeline Height (Diameter in...) 100
Pipeline Width (mm)

Line Length (m)
Material Earthenware
Shape Circular Pipe
Joint Spacing

Material Change, EW TO PVC

Position 6.59m

Code abbreviations MC

Damage category

11:47:55 02-26-2021

6.48m

171 Taylor Street > 1332648

Joint, Displaced, Small, Jointing method has moved .

Position 6.59m

Code abbreviations JDS

Damage category

0

11:47:55 02-26-2021

6.48m

171 Taylor Street > 1332648



"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACUUM LOADING AND SEPTIC TANKS



facebook.com/AssassinDrainageSolutions

assassin.co.nz

PH:0800 938 538

Contract No.

Image report pipe

Parallel Line

Asset No. 171 Taylor Street
Upper Node 171 Taylor Street
Lower Node 1332648
Pipeline Height (Diameter in...) 100
Pipeline Width (mm)

Line Length (m)

Material

Earthenware

Shape

Circular Pipe

Joint Spacing

Line Deviates, Right

Position 6.81m

Code abbreviations LR

Damage category



Line Deviates, Left

Position 7.98m

Code abbreviations LL

Damage category





"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACCUM LOADING AND SEPTIC TANKS

f facebook.com/AssassinDrainageSolutions assassin.co.nz PH:0800 938 538

Image report pipe

Contract No.

Parallel Line

Asset No. 171 Taylor Street
Upper Node 171 Taylor Street
Lower Node 1332648
Pipeline Height (Diameter in...) 100
Pipeline Width (mm)

Line Length (m)

Material

Earthenware

Shape

Circular Pipe

Joint Spacing

Material Change, PVC TO EW

Position 8.24m

Code abbreviations MC

Damage category

11:48:10 02-26-2021

8.24m



Construction Feature, 11-1 o'clock Inspection Lid.

Position 23.77m

Code abbreviations CF

Damage category

11:50:38 02-26-2021

23.77m





"It's A Dirty Job But Someone Has To Do It!"

- JETTING & CLEANING WORKS
- CCTV MAINLINE UPTO 2.3M DIAMETER
- CCTV PUSH ROD CAMERAS
- TRACE AND LOCATING
- SUBDIVISIONS AND FAULT DIAGNOSIS
- VACCUUM LOADING AND SEPTIC TANKS



facebook.com/AssassinDrainageSolutions

assassin.co.nz

PH:0800 938 538

Contract No.

Image report pipe

Parallel Line

Asset No. 171 Taylor Street
Upper Node 171 Taylor Street
Lower Node 1332648
Pipeline Height (Diameter in...) 100
Pipeline Width (mm)

Line Length (m)

Material

Earthenware

Shape

Circular Pipe

Joint Spacing

Line Deviates, Down

Position 24.91m

Code abbreviations LD

Damage category

11:50:46 02-26-2021

24.80m

171 Taylor Street > 1332648

Inspection Ends, Connection to Main .

Position 25.49m

Code abbreviations IE

Damage category

11:50:53 02-26-2021

25.49m

171 Taylor Street > 1332648

APPENDIX E

Application Plan

COPYRIGHT: THE COPYRIGHT AND INTELLECTUAL PROPERTY RIGHTS OF THE INFORMATION SHOWN ON THIS PLAN REMAIN THE PROPERTY OF KOTARE CONSULTANTS LTD. IT MAY NOT BE REPRODUCED WITHOUT THE PRIOR CONSENT OF KOTARE CONSULTANTS LTD. AREAS AND DIMENSIONS SHOWN ARE SUBJECT TO FINAL SURVEY.



PROPERTY DETAILS:	
LEGAL DESCRIPTION:	
LOT 4 DEEDS 605	
- AREA: 1012m2	
- RT SA1404/6 Ltd	
- WAIPA DISTRICT COUNCIL	
- ZONING: RESIDENTIAL	

NOTES:	
1. HEIGHTS ARE IN TERMS OF MOTURIKI VERTICAL DATUM 1953 (MOT53)	
2. DATUM NAIL IN SEAL RL = 67.72	
3. CONTOUR INTERVAL = 0.1m	
4. AREAS AND DIMENSIONS SHOWN ARE SUBJECT TO FINAL SURVEY.	



PLAN TITLE	
SUBDIVISION APPLICATION PLAN	
LOTS 1 and 2 Being a Subdivision of	
LOT 4 DEEDS 605	
At 171 TAYLOR STREET, CAMBRIDGE 3434	
ERROL MURRAY HALL	

REVISION	Rev0 Original	30 MAR 2021	JOB	1014	SHEET	01
DATE	30 MARCH 2021		SCALE AT A3	1:150	Rev	0
CAD	CPM					