

Asset Property Inspections



59 Morningside Road, Morningside,
Whangarei

Laura Welsby



Residential Property Inspection

Prepared for: Laura Welsby

Inspection date: 11th April 2024

Inspection address: 59 Morningside Road, Morningside, Whangarei

Weather conditions: Fine

Inspection carried out by: Simon Watts – Asset Property Inspections

Attachments:

- Electrical Report – N/A
- Property Records from Whangarei District Council – N/A
- Methamphetamine Screen Test Report – N/A

Table of Contents

| | |
|--|----|
| 1. Disclaimer | 4 |
| 2. Referenced Documents | 6 |
| 2.1 New Zealand Standards | 6 |
| 2.2 New Zealand Legislation..... | 6 |
| 2.3 Other Documents..... | 6 |
| 2.4 Latest Revisions | 6 |
| 3. Exclusions..... | 6 |
| 4. Definitions..... | 7 |
| 4.1 Reasonable Access | 8 |
| 5. Interpretation..... | 9 |
| 6. Equipment Used | 9 |
| 7. The Property Inspection Report | 9 |
| 7.1 Purpose of the property inspection..... | 9 |
| 7.2 The property report | 9 |
| 7.3 Summary of property details | 10 |
| 8. Abbreviations | 10 |
| 9. Summary | 11 |
| 10. Moisture Reading Report | 12 |
| 11. The Property Inspection..... | 14 |
| 12. Inspection Report detail | 24 |
| 13. Other systems..... | 34 |
| 14. Definitions of Weathertightness..... | 35 |
| 14.1 Definitions Note | 36 |
| 15. Certificate of inspection in accordance with NZS4306:2005..... | 37 |

1. Disclaimer

Asset property inspections Ltd agrees to perform a visual inspection. The client, as listed above, engaged Asset Property Inspections Limited to prepare a residential property inspection report with the conditions and understanding as listed below.

The report is for the specific address and to the client only and to be used exclusively for the client's own information and may not be relied upon by any other person.

The client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part to a third party. The client may distribute copies of this report to the vendor and real estate agents directly involved, but said persons are not specifically intended beneficiaries of this agreement or the inspection report.

The client agrees to indemnify, defend and hold the inspector harmless from any third-party claims arising out of the clients unauthorised distribution of the inspection report.

This report remains property of Asset Property Inspections Ltd and must not be reproduced in any way without our written permission.

These terms and conditions apply to the inspection undertaken by Asset property inspections and the Inspection Report to which these terms and conditions apply. Inspections are undertaken by Asset property inspections in accordance with Residential Property Inspection Standard NZS 4306:2005. Purpose of Inspection and Scope The inspection report prepared by Asset property inspections to which these terms and conditions apply (Inspection Report) is prepared for the client to whom the Inspection report is addressed (Client), and is based on an above ground visual non-invasive inspection of the building or dwelling to which the Inspection Report relates (building). The Inspection Report has been prepared to provide general comments on the condition of the components of the building at the time of the inspection only. The Inspection Report and the inspection are subject to any express instructions received from the Client. The Inspection Report is not a specific structural survey, engineer's report, weather tightness inspection or any form of guarantee or warranty as to the fitness of the building. If the Client requires a structural survey, engineer's report, weather tightness inspection or other inspection from a third-party specialist, Asset property inspections can assist with arranging such specialist third party inspection upon request. As the purpose of this inspection was to assess the general condition of the building based on a limited visual inspection described below, the inspection may not identify all past, present or future defects. Descriptions in the Inspection Report of systems or appliances relate to the existence of such systems or appliances only and not the adequacy or life expectancy of such systems or appliances. Any area or component of the building or any item or system not specifically identified in this report as having been inspected was not included in the scope of the inspection. The Client accepts that Asset property inspections will not detect some faults because the fault only occurs intermittently; part of the building has not been used for a while and the fault usually occurs after regular use (or detection of the fault would only occur after regular use); the type of weather that would normally reveal the fault is not prevailing at, or around, the time of the inspection; the fault has been deliberately concealed; furnishing are obscuring the fault (see below); Asset property inspections has been given incorrect information by the Client, the vendor (if any), the real estate consultant, or another person; and/or the fault is/was not apparent on a visual inspection.

Visual Inspection

While all care and effort is taken to discover and record irregularities and defects in the building at the time of the inspection, Inspection Reports are based on a visual above-ground non-invasive inspection only. Due to the size, complexity and hidden nature of construction, irregularities and defects may not always be visible at the time of the inspection. Asset property inspections accepts no responsibility or liability for an omission in the inspection or the Inspection Report related to defects or irregularities which are not reasonably visible at the time of the inspection or which relate to components of the building which are below ground. The Client accepts that the visual inspection is limited to those areas of the building which are reasonably and safely accessible at the time of the inspection. Asset property inspections has not opened up, uncovered or dismantled any part of the building part of the inspection or undertaken any internal inspection of the building. The inspection did not include any areas or components which were concealed or closed in behind finished surfaces (such as plumbing, drainage, heating, framing, ventilation, insulation or wiring) or which required the moving of anything which impeded access or limited visibility (such as floor covering, furniture, appliances, personal property, vehicles, vegetation, debris or soil). Asset property inspections did not move occupier-owned items for the purpose of undertaking the inspection. Asset property inspections is not responsible for inspecting, and the inspection will not cover, any part of the building or property to which access is not reasonably and safely available to carry out a visual inspection. This may include roofs, subfloor areas and ceiling cavities. High, constricted or dangerous areas cannot be inspected if in conflict with Occupational Safety and Health Regulations. Product names, materials and systems are generalized to help in reading and understanding the inspection Report. All materials and systems are assumed to be standard typical construction or materials when not able to be fully investigated (whether for the reasons stated above or for any other reason). Compliance with Statute Regulations, Territorial or Other Relevant Authorities Unless otherwise stated, Asset property inspections has not and will not make any inquiries or undertake any inspection of any third party, territorial or other relevant records in respect of the building. The Inspection Report does not replace and is not intended to replace a council issued Land Information Memorandum or Council file search. Asset property inspections recommends a Land Information Memorandum report is obtained and Council file search conducted. If the Inspection Report contains any information obtained from the Council, then such information is only as accurate as the Council information on which such information is based. Asset property inspections accepts no responsibility for any error or omission in such information as a result of inaccurate Council records. Asset property inspections makes no representation that the building complies with requirement of any legislation (including any act, regulation, by-laws, etc), including but not limited to the Building Act 2004, Health and Safety in Employment Act 1992, Fire Safety and Evacuation of Building Regulations 2006 or the Disabled Persons Community Welfare Act 1975. The Inspection Report is not a site or environmental report and ABI makes no representation as to the existence of or absence of any "contaminant" (as that term is defined in the Resource Management Act) or any "hazard" (as that term is defined in the Health and Safety in Employment Act) in the building or property. Title and Boundaries Asset property inspections has not undertaken a search of the title

Asset Property Inspections Limited

2. Referenced Documents

2.1 New Zealand Standards

| | |
|----------------------|---|
| NZS 3019:2004 | Electrical installations – In service testing |
| NZS 3604:1999 | Timber framed buildings |
| NZS 4218:1996 | Energy efficiency – Housing and small building envelope |
| NZS 5261:2003 | Gas installation |

2.2 New Zealand Legislation

Building Act 2004

Unit Titles Act 1972

2.3 Other Documents

Department of Building and Housing: The New Zealand Building Code and Approved Documents of the building code, Clause E2/AS1 External Moisture (Version 1 2005)

2.4 Latest Revisions

The users of this Standard should ensure that their copies of the above-mentioned New Zealand Standards and referenced overseas Standards are the latest revisions or include the latest amendments. Such amendments are listed in the annual Standards New Zealand Catalogue which is supplemented by lists contained in the monthly magazine Standards, issued free of charge to the committee and subscribing members of Standards New Zealand.

3. Exclusions

Except as provided for in 4.3, this Standard does not cover the following:

1. Legal title;
2. Building warrant of fitness and services described on a compliance schedule;
3. Planning, resource consent issues;
4. Building consent issues;
5. Long term maintenance planning;
6. Rental property tenancy inspections;
7. Heritage obligations; and
8. Compliance with body corporate rules, the terms of a memorandum of cross lease or
9. A company title occupation agreement.

4. Definitions

For the purposes of this Standard, the following definitions shall apply:

Accessory Unit(s) (as defined in the Unit Titles Act). Any area, usually with a specified purpose, which does not comprise part of the dwelling unit footprint, but is intended to be used in conjunction with the unit.

Note – Costs may be the exclusive responsibility of the owner(s) of the dwelling(s) whose titles records their interest in the accessory unit. Such unit might be a garage, carport, carpark, and deck, garden, implement shed, landing, service area or access way.

Ancillary Spaces and Buildings. Any area, usually with a specified purpose, which does not comprise part of the dwelling unit footprint.

Common Property. An area that is owned collectively by all the unit owners and defined as such in the relevant documents.

Note – Individual owners have no particular right to any part of the common property and their interest is not recorded on their title; however, all unit owners are responsible for paying their proportionate share of the outgoings. Areas of common property can include gardens, driveways, access ways, roofs, the exterior fabric of the building, service areas, ducts, the unit occupied by the resident manager; shared building services such as lifts, boiler and water reticulation systems, fire protection and ventilation systems and recreation areas such as gym, tennis court, swimming pool or roof garden.

Inspector. A person, partnership or company qualified and experienced to undertake property inspections.

Minor Fault or Defect. A matter which, in view of the age, type or condition of the residential building, does not require substantial repairs or urgent attention and rectification and which could be attended to during normal maintenance.

Note – Minor defects are common to most properties and may include minor blemishes, corrosion, cracking, weathering, general deterioration, unevenness, and physical damage to materials and finishes.

It is common for most of these defects to be rectified over the first few years of ownership as redecoration and renovation are undertaken.

Multi-Unit Property (ies). Any property that accommodates more than one residential dwelling unit and where the owners have collective obligations.

Note – Multi-unit properties will usually be owned under a body corporate, cross lease or company title where the relevant legislation along with the body corporate rules and unit plan, memorandum of lease and flat plan or constitution and occupation agreement define the areas of individual and collective responsibility.

Property Inspection. A non-invasive visual inspection of a residential building carried out in accordance with 2.3.

Reasonable Access. Areas where safe, unobstructed access is provided and the minimum clearances specified in table 1 are available; or where these clearances are not available, area within the inspector’s unobstructed line of sight.

NOTE – It shall be clearly stated if no access was available, or access to limited areas only was available at the time the inspection was carried out.

4.1 Reasonable Access

| Area | Access manhole (mm) | Crawl space (mm) | Height |
|---------------|---------------------|---|--------------------------------|
| Roof space | 450 x 400 | 600 x 600 | Accessible from a 3.6m ladder* |
| Subfloor | 500 x 400 | Vertical clearance <ul style="list-style-type: none"> • Timber floor: 400** • Concrete floor: 500 | |
| Roof exterior | | | Accessible from a 3.6m ladder* |

- *Or such other means of access that meet OSH requirements
- **From underside of bearer.

Significant Fault or Defect. A matter which requires substantial repairs or urgent attention and rectification.

Survey. A separate, detailed inspection and report that may require invasive and/or specialised testing equipment, and may require the specialist knowledge of a relevantly qualified expert.

5. Interpretation

- The word “shall” identifies a mandatory requirement for compliance with the Standard.
- The word “should” refers to practices which are advised or recommended.
- When Cross-referencing to other clauses or clause subdivisions within this standard, the number is only quoted.
- The full titles of referenced documents cited in this Standard are given in the list of “Referenced Documents” immediately preceding the Foreword.

The terms “Normative” and “Informative” have been used in this Standard to define the application of the Appendix to which they apply. A ‘Normative’ Appendix is an integral part of a Standard whereas an “Informative” Appendix is only for information and guidance. Informative provisions do not form part of the mandatory requirements of the Standard.

6. Equipment Used

| | |
|------------------------------|--------|
| Ladder | Torch |
| Moisture Meter – Trotec T660 | Camera |

7. The Property Inspection Report

7.1 Purpose of the property inspection

The purpose of the property inspection is to identify significant defects visible at the time of the inspection.

7.2 The property report

Section 3.2 of NZS 4306:2005 states that the Property Report shall include the following:

| | |
|---|---|
| Address of property the property report relates to | 59 Morningside Road, Morningside, Whangarei |
| Name of person requesting report | Laura Welsby |
| Name of inspector | Simon watts LBP |
| Weather at time of inspection | Fine |
| Date or dates of the inspection | 11 th April 2024 |

- Any area or item which was not inspected and the reasons which prevented an inspection, and if appropriate, a recommendation for further investigation;
- A summary which includes an opinion as to the overall condition of the dwelling in the context of its age, type and general expectations of similar properties;
- A list of any significant faults or defects;
- Advice of any further inspections deemed necessary, such as those carried out by an electrical inspector, plumbing and drainage inspector, engineer, or surveyor; and

7.3 Summary of property details

| Description | Details |
|-----------------------------------|--|
| Building Type | This is a residential dwelling |
| Year of construction | Not known the property files were not reviewed |
| Property Occupied | The property was occupied |
| Construction Type | Timber framed |
| Footings Type | Concrete piles with timber jack framing |
| Wall Cladding | Weatherboards |
| Roof Design | Timber framed |
| Roof Cladding | Corrugated profile metal |
| Storeys | Single storey |
| Direction that house faces | The living area faces west |

8. Abbreviations

The following abbreviations are used in this Standard.

| | |
|-------------|--------------------------------------|
| ° | Degrees |
| CCTV | Closed Circuit Television |
| EIFS | External Insulation Finishing System |
| m | Metre |
| mm | Millimetre |
| OSH | Occupational Safety and Health |
| PCBs | Polychlorinated Biphenyls |
| RCD | Residual Current Device |
| uPVC | Unplasticised Polyvinyl Chloride |
| WC | Water Closet |

9. Summary

General Summary

The dwelling is constructed on a slightly sloping site and is supported over concrete piles with timber jack studs.

It appears that the original dwelling has been re-piled in-situ and we did not see any significant issues around the piles however we cannot verify the size and suitability of any foundations that cannot be seen.

We did not see any significant damage or decay in the visible subfloor framing and the ground conditions are dry with no signs of surface water draining into the subfloor

The subfloor is installed with foil insulation, and this prevents a visible inspection of the underside of the flooring therefore we cannot confirm the condition of the flooring and framing above the foil insulation.

The property is in reasonable original condition with remedial, cosmetic and maintenance issues that are consistent with age and should be addressed on an ongoing basis

It would be fair to say the dwelling has been partly renovated and the issues noted are consistent with a dwelling of this age and would be considered as fair and ongoing maintenance requirements to ensure and prolong durability.

The dwelling is timber framed with original native timber weatherboard cladding – we noted the walls are in alignment with no significant issues seen.

Structure is beyond the scope of this report however we did not see any signs of cracking or ground creep that would indicate there are any issues around the foundation design.

Surface water appears to be controlled onsite and does not appear to be an issue – we did not see the dwelling in a storm event.

All clearances to ground levels are fair and we did not see any issues in this area.

The front and rear decks are reasonable and have recently been renovated however we did note the piles supporting the rear decks are decaying and are due an upgrade for safety soon.

The corrugated roof cladding is not original and is in reasonable condition, all valleys, ridge and hip caps are secure and suitable for the wind zone. We have recommended some remedial maintenance and chemical washing to remove any lichen build up. This is considered ongoing maintenance to preserve condition and is not a defect.

The original external cladding has some areas with cosmetic splitting and paint deterioration however we noted no significant decay.

The timber windows are also original and are beginning to deteriorate in parts.

We advise that ongoing maintenance is critical to ensure weathertightness and prolong durability. The joinery is a mix of original sliding sash and later added timber casement windows are installed around the rear addition.

We did not detect any elevated moisture readings or note any visible signs of water ingress in or around the timber joinery.

We did not see or record any evidence of moisture at the sides of the showers.

The dwelling LIM report was not reviewed, and we recommend this is checked to ensure what is recorded on the property file matches what is constructed on site.

We recommend ongoing maintenance is critical to ensure durability and weathertightness around older timber framed dwellings.

10. Moisture Reading Report

The following indicators can be used for moisture orientation – recorded digits must be read in conjunction with the information below

| Display (digits) | Building Material Moisture Range |
|---------------------|----------------------------------|
| Less than 40 digits | Dry |
| 40 to 80 digits | Damp |
| Over 80 digits | Wet |

Actual moisture readings

| | |
|---------------|-------|
| Bedrooms | 36-45 |
| Bathrooms | 40-93 |
| Lounge | 32-36 |
| Kitchen | 39 |
| Dining/living | 23-31 |

Common Digit values for NZ conditions

Trotec T660 Moisture Meter is used for the testing of moisture levels in the dwelling.

The device is held up against the wall, timber or concrete and the unit scans up to 40mm from the surface.

Where moisture is located, the readings from the meter will increase significantly. (Note: Metal also increases the readings of capacitance meters)

Measurement Method: Capacitance - Di-electric Measurement Range: 0-200 digits.

The measurement is affected according to the dielectric measuring principle.

* The measurement results are only to be used as reference for a rough orientation.

* An important variable influencing the measured value is the bulk density of the goods to be measured. The higher the bulk density, the higher the measure value.

*If the material to be measured contains metals (e.g. nails, screws, lines, pipes etc.) and is situated within the sensor's measuring field, the measured value skyrockets. In that event the measurement is not conclusive.

*With material thicknesses of less than 20mm there is a danger of humidity values adjacent material layers affecting the measured value.

MEASURED VALUE ASSESSMENT FOR WOOD

0>50 = Dry

>80 = Limit to the saturated range.

Since the measurement value displays of the dielectric measurement method - depending on marginal conditions - are subject to great fluctuations, a resistance measurement is always preferable, in particular for the determination of wood moisture.

MEASURED VALUE ASSESSMENT FOR BUILDING MATERIAL For building materials the measurement results of the dielectric measuring method can only be used as reference for a rough orientation. Conclusions with respect to absolute humidity in mass % (M%) can only be drawn for measurements, performed with the exact same marginal conditions and compositions of the building materials as indicated for the test set-up in the chart below.

Typical readings for Gib covered, radiata pine framed internal walls 30-40 digits

Typical common values for Skirted, gib covered radiata pine bottom plates 35-40 digits

Typical common values for carpet, underlay covered concrete floors 50 to 60 digits

Typical common values for bare or exposed concrete over 100 digits

Conversion of digits to %

Manufacturers do not have a conversion for this, however as an estimated guide, for a typical New Zealand Gib covered timber framed internal wall 40 digits = approx. 15% WM in the timber frame.

11. The Property Inspection

Property Photos



The main entry is located at the front south facing elevation



Side east facing elevation with driveway access and parking



The decks and gardens are located at the rear northern elevation



Western side elevation with damaged fencing and ancillary dwelling against the boundary

Property Photos



The cladding is original with some splitting and deterioration consistent with age and wear



Timber base boards with gaps allow good crossflow ventilation in the timber subfloor



Deterioration and missing glazing putty in the windows are now due for renovation and repairs



Deterioration and some decay in the external trims that will require ongoing maintenance and repair



The timber soffit lining is deteriorated the soffit are reasonable however maintenance is needed



Exposed outriggers and timber sarking soffits are reasonable with no significant defects noted

Property Photos



The front and rear decks are due some work around the foundations and jack framing



Decay and out of plumb piles noted below the rear elevation decks, repairs are due soon



Formed concreted drive with some deterioration and slumping requiring upgrades and repair



The timber fencing at the boundary has failed and is leaning into the property



This ancillary building is on the boundary and is discharging water runoff to the adjacent dwelling



Windows provide passive ventilation and natural light into the attic conversion

Property Photos



The corrugated roof is a reasonably new and is suitable for the design, location and wind zone




The roof should be cleaned and chemwashed to inhibit lichen growth and preserve condition



Back soakers trays, apron, ridge and hip flashing are securely fixed and suitable for the roof



The external Upvc gutters are clean and clear with suitable fall to the outlets



The apron flashings are face fixed and rely on silicone to be weathertight – maintain the silicone



The barge and ridge flashings are secure, and the soft edges are moulded down to the roof surface

Property Photos



Traditional timber framing with several old remedial repairs provides the roof support



Building paper is installed to control condensation from the underside of the new profile metal



A ventilation and heat recovery unit is installed to provide positive dry air pressure into the dwelling



Part of the original roof cavity has been converted into attic space – we cannot verify this old work



The walls and ceilings are correctly insulated around the bedroom with a sarked skillion roof



Our inspection is visible and from the access hatch we do not enter the roof cavity

Property Photos



concrete piles with timber jack studs provide the foundations, the dwelling has been re-piled



The visible subfloor framing is original and is dry and well ventilated with no significant issues seen



The subfloor is fitted with foil insulation which prohibits a view of the underside of the flooring



The concrete piles indicate a full re-pile, we did not feel any obvious deviation in the floors underfoot



A ground vapour barrier is fitted to inhibit rising damp and moisture below the dwelling



The dwelling appears to have been replied, we cannot verify the size or suitability of the footings

Property Photos



Bedroom 1



Dry moisture readings located around bedroom 1 windows



Bedroom 2



Dry moisture readings located around bedroom 2 window



Bedroom 3



Dry moisture readings located around bedroom 3 window


Property Photos



Bedroom 4



Dry moisture readings located around bedroom 4 window



Recently fitted mains pressure cylinder -consider adding seismic restraints and a safe tray here



Dry moisture readings in the flooring indicate no leaking from the cylinder or valves in this area



Lounge with free standing wood fire installed as the fixed heating and cooling



Dry moisture readings located around the lounge windows and walls below the flue

Property Photos



Kitchen with mechanical ventilation installed over the stove



Dry moisture readings located around the kitchen windows and cabinetry below the sink



Family bathroom with acrylic bath



Dry moisture readings located at the bath to wall junction indicating the liner is correctly sealed



Bathroom 2



Elevated moisture at the shower to wall junction can indicate the liner is not correctly sealed here

Property Photos




Timber batted ceiling linings with diffuser providing filtered dry air into the dwelling



Heat recovery and ventilation system control panel



Wood fires must be checked and serviced annually by accredited installers



We did see old borer holes in the flooring, we did not see any live borer in the visible areas

ASS

12. Inspection Report detail

Key to inspection report

| | |
|--|--|
| | Not Inspected |
| | Satisfactory |
| | Cosmetic Only |
| | Some Risk Requires Maintenance or Monitoring |
| | Needs Repair |

General Site Features

| Feature | Description |
|--|---|
| Orientation of living area | The living areas are west facing |
| Site exposure, contour and vegetation | <p>The site is located in a high wind zone and low risk stability hazard zone.</p> <p>The property is also identified as flood susceptible however this is not accepted by WDC</p> |
| Paths steps and driveways | Formed concrete and asphalt drive and parking with cracking and displacement. This appears to be age and wear and not from a significant structural event |
| Fencing | <p>Timber fencing is installed along some of the boundary elevations</p> <p>We noted parts of the fencing are leaning out of plumb and failing the fencing will require repair and ongoing maintenance consistent with wear</p> <p>The ancillary building at the boundary is discharging its stormwater onto the neighbouring property and this should also be fire rated if it is to remain on the boundary</p> <p>There is some risk with this shed at the boundary</p> |
| Surface water control | <p>Surface water appears to be controlled onsite and flows away from the dwelling.</p> <p>The dwelling is raised around 600mm off the ground, and we did not see any areas at risk of surface water ingress.</p> <p>The subfloor ground condition is dry however the site is identified as a potential flood risk</p> |

The Foundation / Subfloor Space

| Feature | Description |
|--|---|
| Timber framing and bracing | <p>The subfloor framing is in original condition and as the subfloor is fitted with foil sisalation which prohibits a view of the entire underside of the native timber flooring and framing therefore condition is unknown.</p> <p>We noted the original parts of the dwelling may have been re-piled insitu and are now supported over concrete piles with timber jack framing and not the original totara piles common at the time of construction</p> <p>This type of insitu re-pile difficult and generally does not keep the floors level and we did note some deviation in the original floors</p> <p>We cannot verify how effective or suitable any new foundation is as we did not complete the work however did not see any significant issues around movement</p> <p>We did note some deviation in level, and this is common in historic building that are well beyond their durability and structural requirements.</p> <p>We did not see any significant defects</p> |
| Plumbing and Electrical | <p>uPVC / Copper water supply with associated wastewater pipes – we noted the new pipework is securely and neatly clipped back in the subfloor</p> |
| Insect and Pest Infestation | <p>We did not see any obvious signs of borer in the visible areas however recommend that due to the amount of native timber in the dwelling it would be prudent to check for borer on a regular basis – we recommend DIY pest control is considered as a preventative measure</p> |
| Access point | <p>Access is limited to crawl space only – the access hatch is located at the eastern elevation</p> |
| Adequacy of ventilation | <p>Timber base boards with gaps to allow crossflow ventilation in the subfloor</p> |
| Ground vapour barrier and subfloor insulation | <p>The dwelling is fitted with foils sisalation.</p> <p>Foil sisalation is now banned because of the risk of electrocution when repairing or replacing this product – we recommend a more efficient subfloor insulation is installed</p> |
| Pile type | <p>The dwelling is fitted with concrete piles with timber jack framing, and this indicates the dwelling has been re-piled. A total re-pile requires an approved consent however this work is likely to predate the building Act 1993, check the LIM for this work</p> |
| Pile to bearer connections | <p>Galvanised wire</p> |
| Obvious structural alteration | <p>A standard inspection does not include a review of the council property file we recommend a review of the LIM or Property file is carried out by the purchaser to compare what is on site and recorded in the plans held by council.</p> |

The Exterior of the Building

Construction and Cladding Type Identification

| | |
|--|--|
| | Not Inspected |
| | Satisfactory |
| | Cosmetic Only |
| | Some Risk Requires Maintenance or Monitoring |
| | Needs Repair |

| Construction type | Attributes & Possible Defects | Comments |
|--------------------------|-------------------------------------|--|
| Construction type | Structural masonry Timber framed | Light timber framed construction, which is suitable for the design and location. |

Construction type

| Construction type | Attributes & Possible Defects | Comments |
|----------------------|--|--|
| Timber framed | Dampness and moisture Verticality and alignment | Timber framing appears to be vertically aligned with no signs of moisture. |

Cladding Condition

| Feature | Attributes & Possible Defects | Comments |
|------------------------------|--|----------|
| Condition of cladding | <p>The timber weatherboards are in reasonable original condition and have clearly been renovated recently.</p> <p>We noted the paint finishes are deteriorated and due an upgrade and ongoing maintenance</p> <p>We did not see any significant defects that could present a weathertight risk.</p> <p>We did see some splitting and deterioration however did not see any evidence of borer or decay in the native timber weatherboards.</p> <p>The original external finishes have been renovated however with older buildings the provision for ongoing planned maintenance is critical to ensure durability and maintaining weathertightness and condition. We did see splitting and deterioration in parts of the external cladding and associated trims however we did not see any significant damage or decay in the visible areas.</p> <p>The dwelling is well beyond any durability requirement and is continuing to perform. Ongoing maintenance is critical with historic dwellings</p> | |

Chimneys, Stairs, Balconies

| |
|--|
| Not Inspected |
| Satisfactory |
| Cosmetic Only |
| Some Risk Requires Maintenance or Monitoring |
| Needs Repair |

| Feature | Attributes & Possible Defects | Comments |
|--|--|---|
| Chimneys | Material type (if possible) Flashings Mortar erosion Verticality | The metal flue is correctly fitted with an aqua seal flashing and soaker tray to meet the current requirements – we recommend the flue and fire are serviced and swept prior to first use |
| Balconies, verandas, patios, decks and pergolas including external stairs | Structure type Location (enclosed space below) Material type (if possible) Flashing Bracing Connection to structure Excessive springiness Balustrades Safety from falling Thresholds (steps down) Clearances of claddings from deck or balcony surfaces Drainage, falls and overflows Waterproofing membrane | The dwelling is fitted with original timber terrace along the main entry and a later added low level deck at the rear The piles supporting the rear deck are out of plumb and are decaying at ground level The decking timber is in reasonable condition and is fit for purpose The piles will require an upgrade soon |

The Roof Exterior

| |
|--|
| Not Inspected |
| Satisfactory |
| Cosmetic Only |
| Some Risk Requires Maintenance or Monitoring |
| Needs Repair |

Roof Material Identification

| Feature | Attributes & Possible Defects | Comments |
|-----------------------|-------------------------------|---|
| Profiled metal | Steel (coated) Aluminium | Corrugated profile metal which is suitable for the design and location. |

Roof Condition – Specific Material Type

| Feature | Attributes & Possible Defects | Comments |
|---|-------------------------------|---|
| Condition – common to all roof systems | | <p>The corrugated profile metal roof cladding is not original and appear to have been installed within the last 10 years</p> <p>The metal corrugated roof is in reasonable condition and all valleys, ridge and hip caps are secure and suitable for the wind zone.</p> <p>We did not see any physical damage or corrosion on the profile metal surfaces and all fixings are secure and correctly installed.</p> <p>We have recommend where the apron flashing are directly fixed to the cladding that the silicone seals are carefully maintained</p> <p>We also recommend the roof cladding is washed down annually with an oxygenated roof wash to remove corrosive salt and dirt build up.</p> <p>This is considered ongoing maintenance to preserve condition and is not a defect.</p> |

Other Roof Features

| Feature | Attributes & Possible Defects | Comments |
|----------------------------------|-------------------------------|---|
| Roof water collection | | The external Upvc gutters are clean and clear with suitable fall to the outlets |
| Downpipes | | Upvc |
| Eaves, fascia and soffits | | Painted timber sarking with timber fascia's and barges with some old surface deterioration and some damaged sarking |

The Roof Space

| Feature | Attributes & Possible Defects | Comments |
|---|-------------------------------|---|
| Access | | Access is provided in through the Attic, our inspection is visible and from the access hatch only |
| Thermal insulation | | Polyester is installed throughout the visible roof cavity to provide R2.9 value insulation |
| Roof under and support | | Building paper is installed below the new roof addition to control condensation from below the roof cladding. There is no building paper below the original dwelling and roof. |
| Roof frame construction and connections | | Timber framed with associated purlins |
| Insect and pest infestation (e.g. borer, birds, rodents) | | We noted no visible signs of live borer in the dwelling. As the dwelling is constructed using native timber framing, we recommend preventative pest control here. |
| Rotting timbers | | No signs of rotting timbers however we did note old water staining in some of the roof members from the original roof. The water staining appears to be dry. |

Building Interior

| | |
|--|--|
| | Not Inspected |
| | Satisfactory |
| | Cosmetic Only |
| | Some Risk Requires Maintenance or Monitoring |
| | Needs Repair |

| Feature | Attributes & Possible Defects | Comments |
|----------------------------------|---|--|
| Ceilings | Material type (if possible) Sagging | Timber board and batten ceiling linings |
| Walls | Material type (if possible) Bulging Nails popping | Plasterboard and original sarking – we cannot verify if there is any original scrim remaining in the walls |
| Timber floors | Material type Damage Noticeably out of level Dampness and moisture damage | Native timber flooring. We did not see the entire floor due to floor coverings and subfloor insulation We did note slight deviation from level across some of the flooring however did not see any significant damage or decay in the original floors. |
| Doors and frames | Door type Binding, loose or badly fitting doors Defective door hardware Damaged doors, frames and finishing's Door stops | Original solid timber doors – we did note some misalignment in isolated door casing, and this is likely to be from historic decay in the original piles and then later re-piling back to level. This is not an issue with significant structural failure |
| Electrical (operation of) | Lights and switches Power outlets | Electricity to the dwelling was connected. Note: we do not carry out electrical inspections for wiring or safety. This must be, by law, carried out by a licenced electrician. We only test to see the electrical switches or lights have power to them at the time of inspection. |
| Heating | Type: Wood fire Location: Lounge | We recommend the fire is checked by an accredited installer and then serviced annually. Further information can be found here https://www.nzhha.co.nz/find-a-service/ |

Interior - Kitchen

| Feature | Attributes & Possible Defects | Comments |
|------------------------------|---|--|
| Bench top | Material type (if possible) Lifting or delamination Damage | Laminate |
| Cabinetry | Material type (if possible) Damage Fittings and hardware Operation of doors and drawers | Melteca |
| Sink | Material type (if possible) Operation of taps Waste/traps Leakage Water hammer Waste disposal unit | Stainless steel. |
| Air extraction system | Mechanical or passive Point of discharge | Opening windows providing passive ventilation and a rangehood providing mechanical ventilation |

Interior – Bathroom, WC, Ensuite

| Feature | Attributes & Possible Defects | Comments |
|-------------------------------|--|--|
| Cistern, pan and bidet | Type and capacity Dual flush Operation Cracking; leakage and staining | Dual flush toilets |
| Bath | | Acrylic bath with proprietary wet wall linings |
| Showers | Leakage Adequacy of flow Wet wall linings Operation of taps and wastes Water hammer Screen material and operation | Acrylic showers with proprietary wet wall linings and glass surrounds. We recorded elevated moisture at the wall and floor junctions around the shower and this can indicate the liner is incorrectly sealed We cannot verify the condition of the framing or flooring in this area, and we recommend further investigation by an LBP or plumber |
| Vanity/washbasin | Material type (if possible) Damage Leakage | Freestanding vanities |
| Ventilation | Mechanical or passive Point of discharge | Passive ventilation by opening windows and mechanical ventilation ducted to the outside environment |
| Flooring | Bathroom Adequate fall to floor waste Material | Seled native timber with vinyl overlay flooring |

Exterior Windows and Doors

| | |
|--|--|
| | Not Inspected |
| | Satisfactory |
| | Cosmetic Only |
| | Some Risk Requires Maintenance or Monitoring |
| | Needs Repair |

| Feature | Attributes & Possible Defects | Comments |
|--|--|---|
| Condition – common to all joinery types | Material type (if possible) Glass type (e.g. safety glass, double glazing, noise reduction, coated) Broken glass Sash and door panel condition Operation and fit Sash and door panel fittings Hardware Security Passive ventilation Facings and trims Flashings | <p>The single glazed timber casement and sash windows are in original condition and have had some renovation however we did note some of the joinery is stiff to operate and some of the windows have deterioration consistent with age and wear.</p> <p>We cannot verify if all of the sash cords are operating</p> <p>We did note that the paint finishes are beginning to deteriorate and some of the glazing putty will need remedial and cosmetic attention.</p> <p>We recommend due to the age of the dwelling the windows and associated facings and scribes are well maintained and the paint finishes remain in good order.</p> <p>This work is considered ongoing maintenance and should be expected with older timber windows – we did not see any major decay present in the windows, facings or trims.</p> <p>We did not see any visible water ingress in or around the windows and doors</p> <p>We recommend ongoing maintenance consistent with the age of the dwelling.</p> |

13. Other systems

| | |
|--|--|
| | Not Inspected |
| | Satisfactory |
| | Cosmetic Only |
| | Some Risk Requires Maintenance or Monitoring |
| | Needs Repair |

| Feature | Attributes & Possible Defects | Comments |
|---|-------------------------------|---|
| Fire warning and control systems. Smoke detector | | Smoke detectors should be installed within 3 meters of all bedrooms and escape routes – we recommend smoke alarms are also fitted in all bedrooms |
| Heating /ventilation systems | | Ventilation system installed in the roof cavity and two high wall heat pumps |
| Electricity services | | Connected to supplier |
| Water services | | Reticulated supply |
| Hot water services | | Mains pressure hot water cylinder with seismic restraints and tempering valve correctly installed |
| Foul water disposal | | Reticulated council sewer |

14. Definitions of Weathertightness

| | | |
|---|----------------|--|
| A: Wind zone | Low risk | Low wind zone as described by NZS 3604 |
| | Medium risk | Medium wind zone as described by NZS 3604 |
| | High risk | High wind zone as described by NZS 3604 |
| | Very high risk | Very high wind zone as described by NZS 3604 |
| B: Number of storeys | Low risk | One storey |
| | Medium risk | Two storeys in part |
| | High risk | Two storeys |
| | Very high risk | More than two storeys |
| C: Roof/wall intersection design | Low risk | Roof-to-wall intersection fully protected (e.g. hip and gable roof with eaves) |
| | Medium risk | Roof-to-wall intersection partly exposed (e.g. hip and gable roof with no eaves) |
| | High risk | Roof-to-wall intersection fully exposed (e.g. parapets or eaves at greater than 90° to vertical with soffit lining) |
| | Very high risk | Roof elements finishing with the boundaries formed by the exterior walls (e.g. lower ends of aprons, chimneys etc.) |
| D: Eaves width¹ | Low risk | Greater than 600mm at first floor level 450-600mm at first floor, or over |
| | Medium risk | 600mm at second floor level 100-450mm at first floor, or over |
| | High risk | 600mm at second floor level 0-100mm at first floor, or |
| | Very high risk | 100-450mm at second floor level, or 450-600mm at third floor level ² |
| E: Envelope complexity | Low risk | Simple rectangular, L, T or boomerang shape, with single cladding type |
| | Medium risk | More complex, angular or curved shapes (e.g. Y or arrowhead) with single cladding type |
| | High risk | Complex, angular or curved shapes (e.g. Y or arrowhead) with multiple cladding types |
| | Very high risk | As for High risk, but with junctions not covered in C or F of this table (e.g. box windows, pergolas, multi-storey re-entrant shapes etc.) |
| F: Deck design | Low risk | None, timber slat deck or porch at ground level |
| | Medium risk | Fully covered in plan by roof, or timber slat deck attached at first or second floor level |
| | High risk | Enclosed deck exposed in plan or cantilevered at first floor level |
| | Very high risk | Enclosed deck exposed in plan or cantilevered at second floor or above |

14.1 Definitions Note

1. Eaves width measured from external face of wall cladding to outer edge of overhang, including gutters and fascia.
2. Balustrades and parapets count as 0mm eaves.

This is sourced from the Department of Building and Housing's Acceptable/solution to the New Zealand Building Code Clause E2/AS1 External Moisture.

Asset Property Inspections

15. Certificate of inspection in accordance with NZS4306:2005

| Certificate of Inspection | |
|---------------------------|---|
| Client name | Laura Welsby |
| Site address | 59 Morningside Road, Morningside, Whangarei |
| Inspectors name | Simon watts LBP |
| Company name | Asset property Inspections |
| Date of inspection | 11 th April 2024 |


| Client name | |
|----------------------------------|---|
| Site | Inspected / not inspected |
| Subfloor/floor | Inspected where visible / not inspected |
| exterior | Inspected / not inspected |
| Roof exterior | Inspected / not inspected |
| Roof space | Inspected where visible / not inspected |
| Interior | Inspected / not inspected |
| Services | Inspected / not inspected |
| Accessory units and outbuildings | Inspected / not inspected |

Any limitations to the coverage of the inspection are detailed in the written report.

Certification:

I hereby certify that I have carried out the inspection of the property site at the above address in accordance with NZS 4306:2005 *Residential property inspection* - and I am competent to undertake this inspection.

Signature:



Date:

15th April 2024

Director/Owner Asset Property Inspections.

An inspection carried out in accordance with NZS 4306:2005 is not a statement that a property complies with the requirement of any Act, regulation or bylaw, nor is the report a warranty against any problems developing after the date of the property report. Refer to NZS 4306:2005 for full details.