


Done

Ian Lowe

From: Authority@goredc.govt.nz
Sent: Friday, 18 March 2016 3:06 p.m.
To: Ian Lowe
Subject: Updated CRM - 3 Waters - Locate Asset-2016/6906



Customer Request (CRM) Summary

The following CRM Task has been updated. Please find the updated request details below for your action.

Request Details

Request Number: 6906\2016
Logged by: Gillian Bedwell
Category: 3 Waters - Locate Asset
Description: Bruce Heslip has been unable to isolate the water supply to the Gore Bowling Club rooms on the corner of Ardwick and Irk Street. He turned the toby tap off but the water was still on in the building. They wish to repair a leaking inside tap in the near future. Could you please take a look at toby tap and also contact Ivan Bagrie (208 8434) Green Keeper or Bruce Heslip (208 4252) so they can be on site to ensure water is turned off to the building.

22 Crombie St.

Customer Details

Customer Name: Bruce Raymond Heslip
Address: 2 Crombie Street GORE 9710
Home Phone: (03) 208 4252
Business Phone:
Mobile:
Email: ngairekh@slingshot.co.nz

Property Details

Address: Address
22B Ardwick Street Gore 9710
22B Ardwick Street Gore 9710

Owner and Address:

Owner & Address

Name And Address Not Found

***** error while
formatting *****

Name And Address Not Found

***** error while
formatting *****

Location Description:

Action / Task Details

Task to be Completed: 3 Waters Officer 2
Action Officer: Tony Mearns
Action Open Date: 18/03/2016
Action Due Date: 12/04/2016
Action Comments: Reallocated to 3 Waters Supervisor (Tony Mearns - 18/03/2016)
Delegated by: Gillian Bedwell
Task Details: [Click here to open and action the task in Authority](#)
CRM Details: [Click here to view the CRM \(Enquiry Screen\)](#)



CRM Response Form



CRM No:

6906/2016

Service

Water



Sewage



Stormwater



Otama RWS



Scheme: _____ Customer: _____ House/Rapid No: _____
Line No: _____ Line Pos": _____ Street/Rd: _____
North: _____ East: _____ Height: _____
Pipe Size: _____ Depth: _____ Material: _____
Tank No: _____ No Units: _____ Depth: _____

Work Done

Service Location



Toby Location



Toby Repair



Reticulation Repair



Clear Blockage



Tank Inspection



Reticulation Fault



Dry Weather Overflow



New Water Conn



Asset Replacement



Surface Flooding



Other



Details: _____

Cause of failure: _____

Pipeline Condition or further work required: _____

Photos Taken: ☐Private Property Affected: ☐Office need to Follow Up: ☐

Arrived at Site:

Date

21/3/16

Time

1020

Finished at Site:

Date

21/3/16

Time

11

Cleaned box out of dirt uncovered top

bowling club
Building

12m

1.3m

Continue Over if Required ☐

3 Waters Team Use:

3 Waters staff member: (Name)

Mick/spudKerb

Contact consumer: Phone



Visit



Date: _____

Time: _____

Details _____




Lateral Capped



225mm Concrete Saddle installation




100mm PVC Lateral connection
to 225mm Concrete Main



100mm PVC Lateral




Water Supply



Front Boundary

22 Crombie Street

Water Supply



22 Crombie Street