

Peter Newton

From: Peter Newton
Sent: Thursday, 10 September 2009 11:15 a.m.
To: 'cozplumbing@xtra.co.nz'
Subject: 140 awamoa road

Marty – 2 things for you here – that pvc drain to hwc requires support in case something sends hot water down it and it becomes flaccid (great word eh) and the 250 outer to the chimney flue requires cross bracing up near the ridge to fully support it off the ceiling plate and to provide stiffening against wind movement as it is pretty high above the roof. Thanks – Eric will be in touch