

DrainMax
Registered Drainlayers
Email: drainmax@hotmail.co.nz

P O Box 2426
Stoke, Nelson 7041
a/h: 035476511

Report for: Philp house. (OBG).
184 Horton's Rd.
Tasman.

Date: 15/5/17 Time: 12:30pm

Council: TDC.

ELECTRICAL				COMMENTS	MATERIALS USED
General Condition	☒ Good	☐ Fair	☐ Poor		
Alarms Tested	Water ☒ Yes ☐ No	Air ☒ Yes ☐ No			
Electrical Compartment Clean	☒ Yes	☐ No			

PRIMARY

Crust Thickness		mm	N/A. New	
Clarification Thickness		mm	N/A. New	
Sludge Thickness		mm	N/A. New	
Inlet Clear	☒ Yes	☐ No		
Sludge Return Operational	☒ Yes	☐ No		
Clean Filter	☒ Yes	☐ No		
Chamber Sound	☒ Yes	☐ No		
Odour	☒ Yes	☒ No		

AERATION

Pump Operational	☒ Yes	☐ No		
Venturis (x2) clear	☒ Yes	☐ No		
Tank Sound	☒ Yes	☐ No		
Inlet Clear	☒ Yes	☐ No		

CLARIFICATION

Clarity Reading	☒ Yes	☐ No	N/A. mm	
Sludge Return Venturi Clear	☒ Yes	☐ No		
Pipework Sound	☒ Yes	☐ No		
Remove Build up of Sludge/Scum	☒ Yes	☐ No	N/A.	
Chamber Sound	☒ Yes	☐ No		

DISCHARGE

Chamber Clean	☒ Yes	☐ No		
Discharge Pipework Sound	☒ Yes	☐ No		
Pump Operational	☒ Yes	☐ No		
Chamber Sound	☒ Yes	☐ No		
Clean Filter	☒ Yes	☐ No		

IRRIGATION FIELD

Buried ☒ Yes ☐ No	Planted Yes ☒ No	Bark/Mulch Covered Yes ☒ No	Ponding Yes ☒ No
Comments: New system. first start up. Irrigation field buried 150mm. deep as per plan. Flush Valves and AAV valve working. fine.			

Service Technician: Richard Nicholls

Signed: 