



8 January, 2001

Please Quote: P27984

Doc No: 165186

Andrew and Josephine Stewart
C/- 15 Morey Street
ROTORUA

FILE

Dear Sir or Madam

RE: VEHICLE CROSSING AND SEDIMENT RUNOFF, 13 MOREY STREET

Following a recent inspection of your vehicle crossing and accessway it was revealed that no vehicle crossing has been constructed and sediment from your accessway is entering the road reserve. The photo taken during the inspection is attached.

The runoff of material onto the road reserve has resulted in complaints from our roading administrators, while also causing problems for stormwater movements along Morey Street. Therefore to bring your vehicle crossing and accessway up to the District Council Standards, and thus preventing the ongoing problem, you need to provide effective on site control of both sediment and stormwater, such that further occurrences are prevented.

For this reason a vehicle crossing needs to be established to the requirements of the Engineering Code of Practice, as detailed in the enclosed Standard Drawing RD13 and RD16 attached. The District Council maybe able to assist you in obtaining quotes for the required work - please contact the District Council if this assistance is required.

We look forward to your co-operation in this matter.

Yours faithfully,

Glen Nicholson
Consents Officer