




Pipe Main
 Pump Supply Main
 Raw Pipe Main
 Rider Main
 Scour Main
 Service
 Abandoned
 Other Assets
 Box Culvert
 Catchpit Lead
 Culvert
 Dish Drain
 Drain Coil
 Kerb & Channel
 Lined Channel
 Overland Flowpath
 Service
 Swale Drain
 Unlined Channel
 Abandoned
 Other Asset
 EDS
 Gravity Main
 Gravity Outfall
 Overflow Line
 Pipe Bridge
 Pressure Sewer
 Rising Main
 Service
 Abandoned
 Other Assets

NZ - Imagery
New Zealand Imagery



Lot 1 4560 SH10 Lake Ohia



Projection NZTM2000. Datum NZGD2000. Scale:1:3,457

DISCLAIMER:
While the Far North District Council strives to keep the data in this service current, it may not be the most recent or most accurate data available. No reliance on the information contained on this map by any person is permitted. FNDC will not be liable for any omissions or errors of information contained on this map. FNDC recommends that persons seek specific advice on individual properties from FNDC and other specialist organisations which may hold more up to date or accurate information.