




Inspection Report #58

Description	Inspection Report 1 - Branthwaite Lot 33
Status	Submitted
Assignee	Alice Chen (ACH)
Date	29-01-2020

Project Details

Project Name	Branthwaite
Project Location	Lot 33
Inspection Location	Foundation excavation
Date / Time of the inspection.	29 Jan 10:00
People / Equipment / Materials / etc on Site	Gottadigg

Weather

Time	Condition	Temperature	Precipitation	Humidity	Wind
28 Jan 06:00	 Cloudy	15°C	0.03 mm	100%	11 km/h
28 Jan 12:00	 Sunny	22°C	0.01 mm	68%	15 km/h
28 Jan 16:00	 Partly Cloudy	23°C	0.0 mm	65%	17 km/h

Information Requests

Tests Requested	Photos Taken	H&S
No	Yes	OK - safe to enter

Inspections

Subgrade OK?	Fill Material OK?	Foundations OK?	Reinforcing OK?	Timber Structure?	Steel Structure?	Masonry
Yes						

Comments

Comments	Other comments
----------	----------------

Completed an inspection of the excavated site. The materials at the base of the excavation was as expected and all topsoil had been removed.

Photos

Project Photos



Status

Confirmation of the status of the works and the requirements for future actions.

Approved to continue? ☒ Yes

Further inspection required? ☐ No

Signed

Signed on
29 Jan 11:25

A handwritten signature in black ink, appearing to read "Lue Chen".