



Worthington's Construction Ltd  
5 Harmony Lane  
Woolston  
Christchurch  
8062

## IDENTIFICATION OF ASBESTOS IN A BULK SAMPLE

Samples received on 14/05/2018 from 13A Brynley Street, Hornby. Sampled by Tom Worthington on 11/05/2018

Results pertain to sample "as received". This report may not be reproduced, except in full.

In-house Method: Based on Australian Standard: AS 4964-2004, Method for the identification of asbestos in bulk samples and HSG 248 The Analyst Guide for sampling, analysis and clearance procedures (2005).

**Asbestos types: Amosite or Brown asbestos, Crocidolite or Blue asbestos, Chrysotile or White asbestos, fibrous Anthophyllite, Actinolite, and Tremolite.**

Asbestos is a hazard. Provided it is incorporated into a stable matrix and no airborne dust is produced it presents minimal health risk. Any asbestos detected follows the definition of "asbestos" (even as a contaminant) in The Health and Safety at Work (Asbestos) Regulations 2016.

DOA: Date of Analysis. Noted for each sample below the sample number.

Where present "A" denotes an amendment and this report supersedes the original report number. This report was reissued to correct an error in sampling information provided by the client.

## Results

Sample # & DOA	Sample Details	Asbestos Types Detected
10299 21/05/18	1 - Lounge/dining - Textured ceiling	No Asbestos Detected
*Comments	Textured coating	

\*Analysts' interpretations and opinions expressed in this report are outside the terms of this Laboratory's Accreditation.

Authorised By:  
Rebecca Lloyd  
Key Technical Person

Reported By:  
Jackie Herring  
Locality Manager



All tests reported  
herein have been  
performed in accordance  
with the laboratory's  
scope of accreditation

Capital Environmental Services (2005) Ltd  
P.O. Box 38-328  
Wellington Mail Centre 5045

2-4 Bell Road South Gracefield Lower Hutt  
Telephone 04-566 3311 Fax 04-566 3312  
Email enquiries@fibres.co.nz www.fibres.co.nz