

RE: Beam fixing

Chambers Consultants - Admin <chambers.consultants@xtra.co.nz>

Mon 14/06/2021 10:39 AM

To: 'Adrian Hart' <conservatoriesbydesign@hotmail.com>

Hi Adrian

Apologies for the delay in getting back to you.

The CP80 Connection as shown is fine, and provides at least as much capacity as the Bowmac brackets previously specified.

Kind Regards,

Kevin Rawlinson



Chambers Consultants Ltd

Civil, Structural and Geotechnical Consulting Engineers

Phone: (64 9) 278 1072 **MOB:** 022 5809598

Email: chambers.consultants@xtra.co.nz

A: 39-41 East Tamaki Road, Papatoetoe

PA: P.O. Box 200-136, Papatoetoe, AUCKLAND 2156

From: Adrian Hart <conservatoriesbydesign@hotmail.com>

Sent: 9 June 2021 10:56 am

To: Kevin Rawlinson <chambers.consultants@xtra.co.nz>

Subject: Fw: Beam fixing

From: Adrian Hart

Sent: Tuesday, 1 June 2021 10:32 AM

To: Kevin Rawlinson <chambers.consultants@xtra.co.nz>

Subject: Beam fixing

Hi Kevin.

Re the job at my house 196 King Street.

Work is completed but inspection today failed.

The builder could not tie the beams to the new studs as per all details provided in the plans.

He use CP80 connectors (See Photo).

Your report 210008.

Council want to have confirmation that these are suitable for uplift. If no an alternative option.

I know you are busy but can you priotise this as my house is very cold and I need to repair the ceilings once this is sorted.

Thanks.

Adrian