

25/1/08

Brick $\frac{1}{2}$ High

Molesal filit Coat

Ties first 2 Course every stud.

Every 3 other.

45 - 50 Canting

Bulldog Wrap all good

Dampcourse on masonry & Paved

Weep holes every 3rd brick

Washouts complete Brick

all ok to Centre

Motor Box under wings again

Shut out Flashings for Liner to Brick Corners

Lintel ~~Beams~~ over Brick Veneer on chimney
end masonry & Flashing under

all ok to Centre

97

Edit Inspections

Inspections #31112

[History...](#)[RFS List...](#)[To View Mode](#)

Status:	Active	ID:	31112
Lodged By:	Kingan, Leanne	Date Lodged:	24-Jan-2008 11:22 AM
Last Changed By:	Herron, Debbie	Date Changed:	24-Jan-2008 11:38 AM
Start Date:	24-Jan-2008 11:19 AM	Category:	Building
Referred From:	General Public	Referral Method:	

Customer Details[Add...](#)

Name:	>>> Contact Search Text <<< .. Remove Update... Set Initial		
	Dooleys Masonry, (Initial Contact)		
Address:	E-Mail:		
Phone (Work):	03 4347091	Phone (Home):	
Cellphone:	0274 320722	Fax:	

Request Details

* Logged by Staff:	Leanne
* TYPE of INSPECTION:	1/2 wall inspection
Consent number:	
* Inspection Sheet & Approved Plans to be on site:	<input type="radio" value="No"/> No <input checked="" type="radio" value="Yes"/> Yes
* Builder and/or Drainlayers names:	Peter Bishop
* Preferred DATE:	25/01/08 or today
* Preferred TIME:	Morning
CONTRACTOR RFS Job Number:	
* INSPECTION SITE:	Fernbrook Rd - Peter Bishop
Details:	Inspection 1/2 wall
Location:	Copy Customer Address
* Is Complaint?	<input type="radio" value="Yes"/> Yes <input checked="" type="radio" value="No"/> No
Urgency:	

Attachments[Repository...](#)[Attach Existing...](#)[Attach New...](#)

No attachments.