

Blog ID: 167723

Author: Casey Port

Created: 2019-11-25 08:54:00

Notes: Casey Port added 'Exemption Issue Awaiting Invoice' block for the following reason:

Blog ID: 167800

Author: Ina Holst-Stoffregen

Created: 2019-11-25 14:04:54

Notes:

RM check complete. No issues for land use.

Blog ID: 171952

Author: Bevan Barker

Created: 2020-01-21 07:38:39

Notes: Branz Wind at Very High

PS1 site specific design High (Accepted as Specific Design)

B1 Structure - Transparency Consulting Andrew Horton. 181283

B2 Durability - Total Span Design Statement

E1 Surface Water - to ground 2m from platform, not to be direct toward boundary

E2 External Moisture - Roof and wall claddings shed water

No planning issues.

Exemption Granted

Blog ID: 171953

Author: Bevan Barker

Created: 2020-01-21 07:44:51

Notes: Bevan Barker removed 'Exemption Issue Awaiting Invoice' block for the following reason:

Block removed to finalise

Blog ID: 171954

Author: Bevan Barker

Created: 2020-01-21 07:45:01

Notes: Bevan Barker added 'Exemption Issue Awaiting Invoice' block for the following reason: Invoice Due
