

Project: Hume House facade refurbishment **Details:** preliminary estimate split 5-9-23

Building: Preliminary design

Item	Description	Quantity	Unit	Rate	Total
	Building facade works				
1	Site preparation				83,715
2	Substructure				0
3	Frame				0
4	External walls & External finish				546,695
5	Windows & External doors				1,004,550
6	Wall finishes				68,500
7	Sanitary plumbing				2,500
8	External works				5,660
9	Sundries				750,000
10	P&G	12	%		295,394
11	Margin	7	%		192,991
12	Contingency	15	%		442,501
	Subtotal				3,392,506
	Fire compliance works				
13	Site preparation				42,345
14	Partitions				3,094
15	Internal doors				8,000
16	Ceiling finishes				67,095
17	Fire services				220,045
18	Electrical services				59,640
19	P&G	12	%		48,026
20	Margin	7	%		31,377
21	Contingency	15	%		71,943
	Subtotal				551,566
	Asbestos works				
22	Site preparation				14,460
23	Roof				62,900
24	P&G	12	%		9,283
25	Margin	7	%		6,065
26	Contingency	15	%		13,906
	Subtotal				106,614
					4,050,686



Project: Hume House facade refurbishment Details: preliminary estimate split 5-9-23 Building: Preliminary design Description Unit Total Item Quantity Rate Site preparation 1 Allowance to disconnect and terminate services where 1 Item 5,000.00 5.000 needed for new works 2 Remove existing windows for replacement including 681 m2 65.00 44,265 frames and reveals 3 137 Allowance to remove interior linings and trim where No 250.00 34,250 needed for window replacement 4 Remove wash hand basin 1 No 200.00 200 83,715 Substructure 1 NOTE: No allowance has been made for work to the substructure including structural strengthening **Frame** NOTE: No allowance has been made for structural upgrades or strengthening External walls & External finish 1 27,760 Allowance to clean and inspect exterior concrete walls 694 m2 40.00 2 Allowance to repair and make good damaged concrete 1 200,000.0 200,000 Item exterior including spalling, cracks, penetrations and old fixing holes 3 Allowance for Sto render cladding including prep. 694 400.00 277,600 m2 substrate layers, coloured finish top coat and waterproofing treatment to window openings 4 Allowance to repaint existing remaining facade including 297 55.00 m2 16,335 prep 25,000.00 5 Allowance to repair or replace damaged flashings 1 Item 25,000 546,695 Windows & External doors 1 137 No 250.00 Allowance to make good window openings for new 34,250 windows 2 605 New thermally broken double glazed windows in 40mm m2 1,400.00 847,000 aluminium frames including hardware and flashings 3 New thermally broken double glazed windows in 125mm 77 m2 1,500.00 115,500 aluminium frames including hardware and flashings 4 Allowance to make good existing remaining glazed 39 m2 200.00 7,800

windows and doors



Project: Hume House facade refurbishment Details: preliminary estimate split 5-9-23 Building: Preliminary design Item Description Unit Total Quantity Rate Windows & External doors (Continued) 1.004.550 Wall finishes 1 137 No 500.00 Allowance to make good wall finishes and trim around new 68.500 windows 68,500 Sanitary plumbing 1 New compliant wash hand basin to accessible WC 1 No 2,500.00 2,500 including compliant tapware 2,500 **External works** 1 NOTE: No allowance has been made for exterior works or landscaping 2 New handrail to existing entrance ramp 12 m 280.00 3,360 3 New central rail to existing balustrade on entrance ramp 12 150.00 1,800 m 4 1 New accessible signage to entrance Item 500.00 500 5,660 Sundries Allowance for scaffold 1 600.000.0 1 Item 600,000 2 Allowance for scaffold lift and secure loading platforms at 1 100,000.0 100,000 Item each storey 3 1 50,000.00 Allowance for temporary protection Item 50,000 750,000 Site preparation 1 Allowance to remove lighting for new sprinklers and fire 497 m2 50.00 24,850 rating 2 497 Allowance to remove ceilings for new sprinklers and fire m2 35.00 17,395 rating 3 Remove interior single door 100.00 100 1 No 42,345 **Partitions** 1 14 New fire rated partition including framing, lining, fire m2 221.00 3,094 stoping and finish 3.094



Project: Hume House facade refurbishment Details: preliminary estimate split 5-9-23 Building: Preliminary design Description Unit Total Item Quantity Rate Internal doors 1 2 No New fire rated interior single door including frame and 3.500.00 7.000 hardware 2 Allowance for existing glazed double doors to be adjusted 1 item 1,000.00 1,000 to open outwards 8.000 Ceiling finishes 1 497 m2 135.00 Allowance for new ceilings to sprinkler extension areas 67,095 67,095 Fire services 1 NOTE: No allowance has been made for upgrades to existing sprinkler supply including pumps 2 Extension of existing sprinkler system to carpark 134 m2 90.00 12,060 3 487 m2 120.00 Extensions of existing sprinkler system to office space 58,440 1 4 Allowance for maintenance to existing fire alarm system 20,000.00 20,000 and emergency lighting / signage 5 Allowance for new fire alarm panel including connection to 1 Item 15,000.00 15,000 existing systems 6 Allowance to fire rate existing penetrations 1 Item 25,000.00 25.000 7 800.00 New illuminated exit signs 1 No 800 8 New supplementary smoke detectors 29 No 90.00 2,610 9 New automatic smoke detection system integrated into 369 m2 55.00 20,295 existing fire safety systems 10 New emergency lighting 823 m2 80.00 65,840 220,045 Electrical services 1 497 120.00 Allowance for new LED lighting to new ceilings m2 59,640 59,640 Site preparation 1 Remove asbestos roof tiles 134 m2 90.00 12,060

2

Remove membrane window box cladding

8 No

300.00

2.400

14,460



Project: Hume House facade refurbishment Details: preliminary estimate split 5-9-23

Building: Preliminary design

Description	Quantity	Unit	Rate	Total
Roof				
NOTE: No allowance has been made for works to main building and meeting building roof cladding unless listed below				
Allowance to make good existing roof substrates under old tiles	134	m2	50.00	6,700
Allowance to make good window box substrates	8	No	500.00	4,000
Allowance for new direct fix cladding to the sides of the mansard roof to match existing	134	m2	300.00	40,200
Allowance for new membrane to the window boxes including upstand apron	8	No	1,500.00	12,000
	NOTE: No allowance has been made for works to main building and meeting building roof cladding unless listed below Allowance to make good existing roof substrates under old tiles Allowance to make good window box substrates Allowance for new direct fix cladding to the sides of the mansard roof to match existing Allowance for new membrane to the window boxes	Roof NOTE: No allowance has been made for works to main building and meeting building roof cladding unless listed below Allowance to make good existing roof substrates under old tiles Allowance to make good window box substrates 8 Allowance for new direct fix cladding to the sides of the mansard roof to match existing Allowance for new membrane to the window boxes 8	Roof NOTE: No allowance has been made for works to main building and meeting building roof cladding unless listed below Allowance to make good existing roof substrates under old tiles Allowance to make good window box substrates Allowance for new direct fix cladding to the sides of the mansard roof to match existing Allowance for new membrane to the window boxes 8 No	Roof NOTE: No allowance has been made for works to main building and meeting building roof cladding unless listed below Allowance to make good existing roof substrates under old tiles Allowance to make good window box substrates Allowance for new direct fix cladding to the sides of the mansard roof to match existing Allowance for new membrane to the window boxes 8 No 1,500.00

62,900

Estimate Total 2,939,199