

Customer Details

Name T.Rogerson

Address 7 Oxford St
Gore

Phone

e-mail

Advise customer of outcome? ☐

Issue Details

Issue ID Issue Description

44007 Replace concrete top, valve leaking on property as per csr43840.

Any directly effected 7 Oxford St
Properties, Streets or Roads?

all 20- Box, man, 1x REC, 1x REC, 1x Brass Cox, 1x olive, 1x nipple, 1x Hens sock.
5.5W 5.2K 350 days

Action Details

Tested 8.3.15 - fine. may have started leaking - recheck before sign off.

Replaced toby 27.5.15 with new 20- cm 2000 manifold - box. Noted copper into property, water leaking along copper pipe into hole from property. Informed owner/resident (male), he said he'd fix at the weekend - top just inside fence on property.

Action Required

Update Intra maps if applicable.

Log Details

Category Water : Toby - Faulty/Leaks

Logged By Tamati Rogerson

Log Date Wednesday, 08 Apr 2015 4:55 PM

Log Method In person

Direct to Essential Services CSR

CC'd to Ian Lowe

CC'd to

Signed Off Details

Signed Off By 0 

Date 27.5.15

**Gore**

District Council

Utilities Service Response Report

CSR No: 44007 Date: 27.5.15

Purpose	New	☒	Repaired	☒	Located	☒
Service	Water	☒	Sewage	☐	Stormwater	☐

Scheme: Urban Customer: _____ House/Rapid No: 7
 Line No: _____ Line Pos: _____ Street/Rd: Oxford St, Gore
 North: _____ East: _____ Height: _____
 Pipe Size: 20mm/20- Depth: 350- Material: Poly street, copper house
 Tank No: _____ No Units: _____ Depth: _____

Work Done	☒	Toby Location	☒	Toby Repair/replace	☒
Service Location	☐	Clear Blockage	☐	Tanks Inspection	☐
Reticulation Repair	☐	New Sewer Conn	☐	Other	☐
New Water Conn	☐				

Details: Replaced toby with new 20- LPM 2000 man. fold & box, owner/resident said they'd fix leak/tap causing water to run along copper from property.


Cause of failure: tobyPipeline Condition or work required: Good/fair

Time arrived at site: _____

Time finished at site: _____

Parts

- 1x 623505
- 1x 582420
- 1x 505118
- 1x 505127
- 1x 504285
- 1x 506183
- 1x 557311
- 1x 509161
- 1x 509239




(Continue Over if Required)

Office Use

Required response time: _____ Reason if outside this time: _____

Contact consumer: Phone Visit Date: 27.5.15 Time: _____Completed by: T. Rogerson (Name) (Signature)

Water Supply



5-3m

7 Oxford Street