

PASS
7/6/2016



Tauranga City



Fencing of Swimming Pools Act 1987

Pool Fencing Inspection Notes

Environmental Monitoring and Compliance

Pool Details

Pool Address: 19 Manson Street

Owner: Kathleen Cranch

Phone: 578 7660

Email: _____

Occupant (if different from owner): _____

Officer Details

Officer Neil Page, Pool Fencing Inspector

Phone 07 5777200 extn 7694, 027 405 0294 Email Neil.page@tauranga.govt.nz

Team Environmental Monitoring and Compliance, Environmental Services

Inspection Record

Pool Consented? ☒ Y / N Consent Number 117834 Date of Consent 1972

Time and Date of Inspection 11.15am 26/2 Time Expended 15min Travel KMs _____

Outcome: Pass ☒ Fail ☒ Re-inspection Required - Refer to attached Inspection Checklist.

Re-Inspection in: 28 Days ☒ 14 Days ☐ 7 Days ☐

Signed by Compliance Officer: _____

Re-inspection - Fully Compliant 7/6

First Inspection



Second Inspection



7/6/2016

Third Inspection



Pool Address

19 Manson Street

Date

26/2/2016

Is the swimming pool full at the time of inspection?

Yes

No

N/A

Is the immediate swimming pool area fenced?

Yes

No

N/A

What is the water source?

Tap

Bore

Is the bore geothermal (>30°C)?

Yes

No

Barrier

- | | | | | |
|----|--|----------|------|-----|
| B1 | The height of the entire barrier is a minimum 1.2m from outside ground level? | Pass | Fail | N/A |
| B2 | There are no permanent projections or objects within 1.2m of the top of the barrier? | Pass | Fail | N/A |
| B3 | The barrier is constructed of durable materials and the construction will inhibit access by a small child climbing over or under the fence? | Pass | Fail | N/A |
| B4 | There is no more than a 100mm space between adjacent steel or timber verticals? | Pass | Fail | N/A |
| B5 | The ground clearance from the base of the barrier is no more than 100mm? | Pass | Fail | N/A |
| B6 | All horizontal or angled braces on the outside of the fence are set a minimum 900mm apart (measured from the top of the lower one to the top of the upper one) any such support structures offer no opportunity to climb the fence from the outside? | Pass | Fail | N/A |
| B7 | The immediate pool area does not contain any features or equipment that would not normally be used in association with the pool, such as a clothesline/play equipment/vegetable gardens etc | Pass 7/6 | Fail | N/A |
| B8 | The immediate pool area does not encompass the whole of the rear section, thereby offering an opportunity to provide areas for other use? | Pass 7/6 | Fail | N/A |

If the barrier is of mesh construction, does it comply with:

- | | | | | |
|----|---|------|------|-----|
| M1 | a) A spacing of 10mm or less for a barrier height of 1.2m, up to 1.8m? | Pass | Fail | N/A |
| M2 | b) A spacing of 10mm-50mm for a barrier height of 1.8m or more? | Pass | Fail | N/A |
| M3 | c) All netting, mesh, shade cloth etc. is firmly attached to the framework? | Pass | Fail | N/A |
| M4 | d) The framework is secure and firmly fixed in the ground, offering no opportunity for access by a small child? | Pass | Fail | N/A |

Gates and Latching

- | | | | | |
|----|--|------|------|-----|
| G1 | All gates that access the pool area only open away from the pool? | Pass | Fail | N/A |
| G2 | There are no obstructions, apparatus or devices used to lodge the gate open? | Pass | Fail | N/A |
| G3 | The gate is hung in a permanent fixed manner with no more than 100mm ground clearance? | Pass | Fail | N/A |
| G4 | An automatic closing device is fitted and the gate self-closes from a static start? | Pass | Fail | N/A |
| L1 | The latching device is of a permanent nature and self-latches when the gate closes? | Pass | Fail | N/A |
| L2 | Any internal latch can only be accessed by reaching over the gate or fence, or through the gate or fence at a height not less than 1.2m from outside ground level? | Pass | Fail | N/A |
| | If an internal latch can be accessed by reaching between verticals in the gate or fence at less than 1.2m, then a shielding device is fitted so that the latch cannot be accessed? | Pass | Fail | N/A |
| L3 | Any external latch can only be reached at a height not less than 1.5m from outside ground level? | Pass | Fail | N/A |

Building Exclusion Devices

Any door in a building, which gives access to the pool area:

- | | | | | |
|----|--|------|------|-----|
| D1 | Is fitted with an automatic closing device so that the door self-closes & self-latches from a static start | Pass | Fail | N/A |
| D2 | The door(s) only open away from the pool | Pass | Fail | N/A |
| D3 | A locking device is fitted at a height no less than 1.5m from indoor floor level. | Pass | Fail | N/A |
| D4 | Any window in a building which gives access to the pool area, with a sill which is less than 1.2m from the indoor floor level, is fitted with a limiter to prevent it opening more than 100mm? | Pass | Fail | N/A |

This swimming pool inspection:

Pass



Fail



(re-inspection required)

7/6/2016

<http://smartzoom2.tauranga.govt.nz/maps/?Viewer=Main>