

Property File:.....

Job history for Code Compliance Certificate No: 97/2108
as at Monday, 28 November 2016

Owner		Site Location				
Cranch T 19 Manson St Tauranga		19 Manson St Greerton Lot 61 D.P. S 8130				
Job Description		Consent				
WorkType Dwelling - Add/Alter IntendedUse Remove wall, fit beam in basement of dwelling		Number 97/2108 Date Thursday, 14 August 1997 Process Time 0. Hrs				
Inspection Summary						
	Required	Done	Passed	Failed	To Be Done	Extra Inspections 2
Building	1	3	2	1	0	
Plumbing/Drainage	0	0	0	0	0	
Structural	0	0	0	0	0	
Total	1	3	2	1	0	

Notes

Inspection Details

Date	Inspector	InspectionType	Result	Note
07/01/98	Bryan Wakelin	Footing	Fail	No one there.
08/01/98	Bryan Wakelin	Footing	Pass	New post pads. Safety glass installed in conservatory roof.
30/01/98	Brian Billing	Final Building	Pass	