

CASH SETTLED CLAIM(S)

The following information contains documents relating to claim(s) that were cash settled for the property.

If you require sign off or repair completion documents, they may be obtainable from the contractors who completed the substantive repairs at the property.

EQC
EARTHQUAKE COMMISSION

ENTERED

Statement of Claim Checklist

Date: 17 Sept 2010Author: BRYAN STAPLESClaim No.: 2010 1055441 077521Claimant: KAIAPOI WORKING MEN'S CLUBSituation of Loss: 103 RAVEN QUAYKAIAPOILA: BRYAN STAPLES Estimator: DOUG TREDINNICK

Room	Damage	Walls	Ceiling	Floor	Description of Damage
	Y/N	✓	✓	✓	
Lounge	Y	✓			Puckering in wall paper
Dining Room	Y	✓		✓	Floor slopping, wall cracking
Kitchen	N				No Damage.
Family Room	N/A				
Bedroom 1	N				No Damage.
En Suite	N/A				
Bedroom 2	Y	✓			Cracking in walls.
Bedroom 3	N/A				
Bedroom 4	N/A				
Bathroom	N				No Damage
Toilet 1	N				No Damage.
Toilet 2	N/A				
Office/Study	N/A				
Rumpus	N/A				
Entry/Hall(s)	N				No Damage
Stairwell	N/A				
Laundry	N				No Damage.
Other ^{Rear} Hall	Y				Cracking in walls

Item		Event Damage	Description of Damage	Appoint Engineer
		Y / N	Y / N	
Roof		N	Rollled Metal	
External Walls	North	Y	MINOR CRACKING to concrete SKIRTING	
	South	Y	BRICK WORK CRACKING with BRICKS MISSING	
	East	Y	liquefaction along base of concrete SKIRTING	
	West	Y	CRACKING in concrete SKIRTING	
Decks / ^{covered} PATIO		N		
Chimney	Base	N	no Damage	
	Ceiling Cavity	N	"	
	Above Roof	N	"	
	Fireplace	N	"	
Foundations		Y	MINOR CRACKING to concrete SKIRTING MINOR liquefaction	
Piling		N		
Services		Y	all Services Still Connected.	
Other Dwelling Items		N/A		
Outbuildings		Y	CRACKS in MORTAR	
Land & Retaining Walls		Y	MINOR liquefaction to East Side	
(Discuss with Supervisor)				

I confirm the rooms and areas listed above have been inspected by an EQC representative.

Damage caused by the event has been noted and to my knowledge there are no other areas of damage resulting from the event.

Signature of Claimant: 

Dated: 17/9/10

ENTERED

Completed By: DOUG TRIPPINICK

Date: 17-9-10

Page 1 of 1

CLM 2010

Claimant Name:

KAIAPOI WORKING MEN'S CLUB

103 RAVIN QUAY. KAIRAOI 7630

Element Details:

Land	<input checked="" type="checkbox"/> Building	<input checked="" type="checkbox"/> Bridges/culverts		Retaining walls		Other	
Lounge	Dining	Kitchen		Family Room		Bedroom	
Office/Study	Rumpus	Hallway		Stairwell		Toilet	
Laundry	Bathroom	Ensuite		Chimney		Foundations	
Piling	Services	Kitchen Ovens		Hot Water Cylinders		Header Tanks	
Glazing/windows	Fireplace/woodburner	Floor		External Walls		Roof	
Outbuildings	Other						

DESCRIPTION: MINOR CRACKING TO WALLS & CEILINGS LAND IN AREA HAS

REPAIR STRATEGY: STABILIZATION OF SOIL LIQUIDATION

LINE ITEMS:

[illegible]

* Unit Categories to be used as follows:

Each, Sheet, Kilogram, Linear metre, Square metre, Cubic metre, Per Hour, Per Day, Per Week. Cubic metre calculations must include length, breadth and depth figures. Square metre calculations must include length and breadth figures.

Subtotal 191.70

1.3662	+ P&G, Margin & GST Figure	70,200.54
--------	----------------------------	-----------

TOTAL 261 900.54

EOC 039 – Revised 07-09

ay 17/9