

CITY OF ROTORUA



Street Damage Claim

VAL./No.: ⁵³⁵656/~~465~~pr.

I, the undersigned, certify that PRIOR TO ANY excavation, earthworks, the depositing of materials, or any other building operations in respect of the below-mentioned site, damage to Council property exists to the following extent.

EXTENT OF DAMAGE

LOT: 4 DPS: 24208 LOCATION: ⁴⁶²Rukehangiri Rd.
footpath is damaged in two places. towards
the left hand boundary and also towards to
right hand boundary looking from the road.
Three cracks in Footpath

SIGNED: N. Dheda DATE: 21.1.81

CHECKED: KDD

DATE: 26/2/81 PPUNIVERSAL HOMES LTD.

P T O

