

CITY OF ROTORUA

Street Damage Claim

VAL./No.:

I, the undersigned, certify that PRIOR TO ANY excavation, earthworks, the depositing of materials, or any other building operations in respect of the below-mentioned site, damage to Council property exists to the following extent.

EXTENT OF DAMAGE


LOT: 121 DPS: 20544 LOCATION: 5 BERYL PL.

CRACK ACROSS LEFT HAND

BACK CORNER.

SIGNED: *M. Bayle* DATE: 6/4/83

CHECKED: _____ DATE: _____



CITY OF ROTORUA

Street Damage Claim


VAL./No.: ~~655~~ 655/959/3

I, the undersigned, certify that prior to any excavation, earthworks, the depositing of materials, or any other building operations in respect of the below-mentioned site, damage to Council property exists to the following extent.

EXTENT OF DAMAGE

LOT: 121 DPS.: 20544 LOCATION: Beryl Place.

Cracks either side of footpath crossing.



SIGNED:

B. G. Wallace DATE: 20/2/81

CHECKED:

KRS

DATE:

26/2/81

CITY OF ROTORUA

Street Damage Claim

VAL./No.: 655/960^{PT}

I, the undersigned, certify that prior to any excavation, earthworks, the depositing of materials, or any other building operations in respect of the below-mentioned site, damage to Council property exists to the following extent.

EXTENT OF DAMAGE

LOT: 121 DPS: 20544 LOCATION: 5. Beryl Place

No damage.

SIGNED

Maddox APL/Homers

DATE 26.4.77

CHECKED: _____

DATE: 26.4.77