

File No

~~2009-0000~~

## OUTSTANDING VEHICLE CROSSING ISSUE

A vehicle crossing serving this property has been identified as not complying with Council's standards

Vehicle Crossing Type

Urban Residential (RD13)

Urban Commercial (RD14)

Rural Residential (RD22)

Rural Commercial / Tanker (RD23)

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Reasons for non compliance

Unformed / unsealed

Sediment / metal runoff onto road


Other

<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Possible future Subdivision

This issue may be followed up under the provisions of Council's Bylaws and the Local Government Act 1974. Details of the non compliance are held by Council's Resource Engineering Section

FILE



Date: 13<sup>th</sup> December 2001

Please Quote: ~~P22200~~  
32774

Mr C Scott  
45A Blomfield Street  
ROTORUA

Private Bag RO 3029  
Rotorua  
New Zealand  
Telephone 07-348 4199  
Fax 07-346 3143  
E-mail mail@rdc.govt.nz

Address all  
communications to:  
District Manager  
Rotorua District Council

Dear Sir

**REFUND OF DAMAGE / VEHICLE CROSSING DEPOSITS**  
**NEW DWELLING – BLOMFIELD STREET, ROTORUA.**

Our Treasury Department has carried out a check of the unclaimed damage/vehicle crossing deposits that are still held by Council.

Your Building Consent No: 92/1558 was identified as one of these.

This deposit was paid to Council at the time of application, some years ago.

Once the crossing(s) have been completed would you please contact this office so that we may arrange an inspection, and if everything is in order, have the money refunded to you.

If we do not receive a response to this correspondence within 14 days these monies could be returned to the Consolidated Fund at the Department of Inland Revenue.

We look forward to hearing from you.

Yours faithfully

Diane Macleod  
Building Administration