

File out to Sid

Rotorua City Council

APPLICATION FOR REFUND OF ~~VEHICLE CROSSING~~ AND/OR
DAMAGE DEPOSIT ON COMPLETION OF WORK

O. J. de VANTIER LTD. . P.O. Box 158, ROTORUA

NAME: J. & B. A. WADE..... ADDRESS: 196... CLAYTON RD.....


RECEIPT NO: 11487..... DATED: 30.7.82... VAL NO: 655/937.....

LOT: 23..... D.P.S: 119..... STREET & NO. OF SITE: 196 CLAYTON RD.

O. J. de VANTIER LTD.

SIGNED: *MacKellar*.....

FOR OFFICE USE



INSPECTION REMARKS:.....
.....
.....
.....

[Handwritten signature]

ESTIMATED COST OF DAMAGE:

INSPECTOR

CITY OF ROTORUA

Street Damage Claim

VAL/No. 655/937

I, the undersigned, certify that prior to any excavation, earthworks, the depositing of materials, or any other building operations in respect of the below-mentioned site, damage to Council property exists to the following extent.

EXTENT OF DAMAGE

LOT: 23 DPS: 119 LOCATION: 196 Clayton Road

Cracking to footpath on both Clayton Rd
and Lisa Crescent concrete footpaths.


PTO

SIGNED: [Signature]

DATE: 7.4.82

CHECKED: [Signature]

DATE: 19/7/82



CITY OF ROTORUA

Street Damage Claim

VAL/No.:

I, the undersigned, certify that PRIOR TO ANY excavation, earthworks, the depositing of materials, or any other building operations in respect of the below-mentioned site, damage to Council property exists to the following extent.

EXTENT OF DAMAGE

LOT: 23 DPS: 911 LOCATION: 196 CLAYTON ROAD
CROSSING IN PLACE IN GOOD ORDER.
CANNER & SONS TO INSTALL NEW CROSSING IN LISA
CRESCENT TO COUNCIL REQUIREMENTS.

SIGNED: 

DATE: 18/6/82

CHECKED: _____

DATE: _____