

Property File:.....

Job history for Code Compliance Certificate No: 11134
as at Monday, 28 November 2016

Owner		Site Location				
Philip Martyn Smith 179B Dickson Rd Papamoa		179B Dickson Rd Papamoa Lot 2 D.P. S 74427				
Job Description		Consent				
WorkType Dwelling - Add/Alter IntendedUse Extend lounge/dining room in dwelling		Number 11134 Date Wednesday, 18 June 2003 Process Time 0. Hrs				
Inspection Summary						
	Required	Done	Passed	Failed	To Be Done	Extra Inspections 0
Building	4	3	2	1	1	
Plumbing/Drainage	0	0	0	0	0	
Structural	0	0	0	0	0	
Total	4	3	2	1	1	

Notes

Inspection Details

Date	Inspector	InspectionType	Result	Note
07/07/03	John Turner	Footing	Fail	Underfloor and slab fail also. Not ready.
08/07/03	John Turner	Footing	Pass	Underfloor and slab okay also.
25/07/03	John Turner	Preline/Building	Pass	

Tauranga City Council: Building Inspections Job Report

Consent/COA No: 11134A

as at Thursday, 24 November 2016

Owner	Site Location																														
Phillip Martyn Smith 179b Dickson Road Papamoa	179b Dickson Road Papamoa Lot 2 D.P. 74427																														
Job Description	Consent																														
WorkType Dwelling - Add/Alter Build. Class IntendedUse Extend lounge/diningroom in dwelling.	Number 11134A Date Tuesday, 14 October 2008 Process Time 0. Hrs																														
Assessments Required																															
<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;"></th> <th style="width: 10%;">Required</th> <th style="width: 10%;">Done</th> <th style="width: 10%;">Passed</th> <th style="width: 10%;">Failed</th> <th style="width: 10%;">To Be Done</th> </tr> </thead> <tbody> <tr> <td>Building</td> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> </tr> <tr> <td>Plumbing/Drainage</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> </tr> <tr> <td>Structural</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> </tr> <tr> <td>Total</td> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> </tr> </tbody> </table>		Required	Done	Passed	Failed	To Be Done	Building	1	1	1	0	0	Plumbing/Drainage	0	0	0	0	0	Structural	0	0	0	0	0	Total	1	1	1	0	0	<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> Extra Inspections 0 </div>
	Required	Done	Passed	Failed	To Be Done																										
Building	1	1	1	0	0																										
Plumbing/Drainage	0	0	0	0	0																										
Structural	0	0	0	0	0																										
Total	1	1	1	0	0																										

Notes

Re-loaded 14/10/2008 Rec number 197671 1 inspection + CCC see BC 11134 for previous inspections.

Inspection Details

Date	Inspector	InspectionType	Result	Note
06/11/08	John Turner	Final Inspection	Pass	final inspection of lounge/ dining room extension passed, Hardi plank exterior ok. Electrical cert to be received. As per plan.20/11/2008 Received electrical compliance certificate.*27/11/08