

Property File:.....

Job history for Code Compliance Certificate No: 96/2232  
as at Monday, 28 November 2016

Owner		Site Location				
S Goodwin 179 Dickson Road  Papamoa		179 Dickson Rd Papamoa  Lot 166 D.P. 21830				
Job Description		Consent				
WorkType Sewerage Connection  IntendedUse Sewer drainage For New Subdivision		Number 96/2232 Date Wednesday, 7 August 1996 Process Time 0. Hrs				
Inspection Summary						
	Required	Done	Passed	Failed	To Be Done	Extra Inspections  0
Building	0	0	0	0	0	
Plumbing/Drainage	1	1	1	0	0	
Structural	0	0	0	0	0	
Total	1	1	1	0	0	

Notes

#### Inspection Details

Date	Inspector	InspectionType	Result	Note
27/09/96	Derek Glover	Drainage	Pass	