

15 February 2022

Adrian Hart
196 King Street
Bay Of Plenty
Whakatane 3120

Dear Adrian Hart,

Reference Number: BC210077

Project Location: 196 King Street

WHAKATANE

Bay of Plenty

Whakatane

3120

Legal description of land where building is located: LOT 1 DPS13256

Project Description: Installation of two beams to allow wall removal

IR Number: 4

Inspection Results:

BUILDING FINAL - 24 Sep 2021 @ 11:10 by Alex Clough

Inspection Outcome: **PASS** - The BCA is satisfied, on reasonable grounds, that the aspects of building work pertaining to this inspection demonstrate compliance with the building consent.

Inspection Summary: CCC assessment carried out, all inspections have now passed, all supporting and required documentation supplied now accepted, CCC applied for may now be issued.

Outstanding Required Documents for this Building

History

Inspection Name

Prepour

Sub-floor Framing

Summary

PASS - 01 Jun 2021

PASS - 01 Jun 2021

Framing / Pre-wrap	PASS - 01 Jun 2021
Preline Building	PASS - 01 Jun 2021
Post Line	PASS - 01 Jun 2021
Building Final	PASS - 15 Feb 2022

Yours sincerely,

Alex Clough
Building Control Officer
On behalf of: Whakatane District Council