

SITE INSPECTION RECORD

67015



TYPE OF INSPECTION		Side Cut inspection	
WJL JOB NO. & REV.		Not a WJL designed Slab	
CIVIL	☐	CONSENT No.	TIBA BC240494
GEOTECH	☒	DATE & TIME	29/4/24 - 2:45
STRUCTURAL	☐	INSPECTOR	BE
ADDRESS			
Lot 44 Lemonwood			
H & S 'Take 5'		JSA No.	Initials
			BE
Site excavated to a 300mm below cut. Exposed material - gravels — all organics removed — scalar containing 30% aggregate — ultimate at base of cut Subgrade ready to accept L100 in 150mm layers WJL engaged to complete subgrade inspection only BE to continue Slab design by others			
SITE CONTACT		COUNCIL INSPECTOR	
PASS ☒			
PENDING ☐			
FAIL ☐			