


ROTORUA DISTRICT COUNCIL

BUILDING PERMIT

Owner: S.N.S.Security
Builder: Chalker & Scott
Type: Work: Garage



Valuation No.: 653/69

Permit No.: A70101

Appn. No.: 3225

Date: 3/12/82

INSPECTIONS

DATE

9/12/82 Lib OK ground & good bearings
OK & pan

16/12/82 job completed

21 -ake Road Street Lot _____ DPS _____ Section _____ Block _____

TO: ADMINISTRATION OFFICER, DEPOT STREET

3225

	Date	Initials
Site Plan Draughting	12-11-82	SPW.
Engineering Design	16/11/82	DDM
Engineering Waste Water	23/11/82	AB
Water Supply	23/11/82	AB

Perusal of the plans and specification has raised the following points ;

Sewerage Connection — This section is already connected
information could be on file.

NOTE: Please briefly describe the problem so the applicant can be advised by letter.
It is suggested that the applicant be advised to make contact with a particular
officer to discuss the fault and remedy.