



Private Bag 3029
Rotorua
Telephone 07 3484199
Fax 07 3453143

FILE

INSPECTION NOTICE

FILE
FAXED

0902

Attn: John Rodgers
Fax 349 0862

File No. P00858
Date: 13.3.98.

TO:

Location of site: Corner Pukutua / Kenoy St.	JOB: Subdivision Building / Development Resource consent Other _____ (state)	Trade Waste Contaminant Litter / Refuse Fill _____ (circle as appropriate)
Weather: <u>Fine</u> Overcast Showers Raining (Circle as appropriate)	Photographs taken: yes / no Location of photograph: _____ Sample(s) taken: yes / no Type: _____	I.D. No: _____
Time of arrival: _____ Duration of visit: 5 min.		

Person(s) spoken to: Developer.

PH:

Observations / Report:

Inspected new connections into
manhole over existing main.
Connections & hanching - O.K.
Lid needs re-concreting on. Concrete

The following action is required to be taken:

Cracked & broken - Lid moving.

still
not repaired 26/5/98
R

Such action must be completed on or before clearance. A reinspection will take place after that date.

Signature: Paul Chung

Name: _____

Position: Revenue Tech

Copy to: Consultant Contractor Owner Occupier File (circle as appropriate)

Delivered by: Mail Fax Hand Other _____ (state) (circle as appropriate)