

Private Bag RO 3029
Rotorua
Telephone 07 3484199
Fax 07 3453143

INSPECTION NOTICE

FILE
FAXED

0902

Attn: John Rodgers
Fax 349 0862

File No. P00858
Date: 13.3.98.

TO :

Location of site: <u>Corner Pukuatua / Ranoff St.</u>	JOB: Subdivision <u>Building / Development</u> Resource consent Other _____ (state)	Trade Waste Contaminant Litter / Refuse Fill _____ (circle as appropriate)
Weather: <u>Fine</u> Overcast Showers Raining (Circle as appropriate)	Photographs taken: yes / no Location of photograph: _____ Sample(s) taken: yes / no Type: _____	I.D. No : _____
Time of arrival: _____ Duration of visit: <u>5 min.</u>		


Person(s) spoken to: <u>Developer.</u>	PH: _____
--	-----------

Observations / Report :

Inspected new connections into manhole over existing main.
Connections & hanching - O.K.
Lid needs re-concreting on. Concrete

The following action is required to be taken:

Cracked & broken - Lid moving.
(not repaired 26/5/98)



REG

Such action must be completed on or before clearance. A reinspection will take place after that date.

Signature: Paula Chung
Name: _____
Position: Resource Team

Copy to: Consultant Contractor Owner Occupier File (circle as appropriate)
Delivered by: Mail Fax Hand Other _____ (state) (circle as appropriate)

INSPECTION NOTICE



Private Bag RO 3029
Rotorua
Telephone 07 3484199
Fax 07 3453143

Attn: John Rodgers
Fax 349 0862

File No. P00858
Date: 13.3.98

TO: P00858

Location of site: <u>Corner Pukuatua / Renoff St.</u>	JOB: Subdivision <u>Building / Development</u> Resource consent Other _____ (state)	Trade Waste Contaminant Litter / Refuse Fill _____ (circle as appropriate)
Weather: <u>Fine</u> Showers Overcast Raining _____ (Circle as appropriate)	Photographs taken: yes / no Location of photograph: _____ Sample(s) taken: yes / no Type: _____	I.D. No: _____
Time of arrival: _____ Duration of visit: <u>5 min.</u>		

Person(s) spoken to: Developer. PH: _____

Observations / Report :

Inspected new connections into manhole over existing main.
Connections & hanching - O.K.
Lid needs re-concreting on. Concrete

The following action is required to be taken:

Cracked & broken - Lid moving
(not to be replaced 20/4/98)

Such action must be completed on or before clearance. A reinspection will take place after that date.


Signature: Paula Chung

Name: _____

Position: Reserve Team

Copy to: Consultant Contractor Owner Occupier File (circle as appropriate)

Delivered by: Mail Fax Hand Other _____ (state) (circle as appropriate)



Private Bag RO 3029
Rotorua
Telephone 07 3484199
Fax 07 3453143

INSPECTION NOTICE

FILE

0540
P00858.

6500/748 P00884
728 P00857
729 P00858
731 P00859

File No: ~~659~~
Date: _____

TO: FILE NOTE

Location of site: <u>Pukiaua / Ranoff Sts</u>	JOB: Subdivision <u>Building / Development</u> Resource consent Other _____ (state)	Trade Waste Contaminant Litter / Refuse Fill _____ (circle as appropriate)
Weather: <u>Fine</u> Overcast Showers Raining (Circle as appropriate)	Photographs taken: yes / no Location of photograph: _____ Sample(s) taken: yes / no Type: _____	I.D. No: _____
Time of arrival: <u>4:15</u> Duration of visit: <u>10 min</u>		

Person(s) spoken to: Developer PH: _____

Observations / Report :

Inspected stormwater connection into existing stormwater system.
Pipe protruding into existing pipe to be relevel level with edge of pipe.

The following action is required to be taken:

As Above.

Such action must be completed on or before clearance. A reinspection will take place after that date.

Signature: Paula Cherry
Name: _____
Position: Resource Technician

Copy to: Consultant Contractor Owner Occupier File (circle as appropriate)
Delivered by: Mail Fax Hand Other _____ (state) (circle as appropriate)



Private Bag RO 3029
Rotorua
Telephone 07 3484199
Fax 07 3453143

INSPECTION NOTICE

6500/748 P00884
728 P00857
729 P00858 *
731. P00859 *

0540
P00858

File No. ~~659~~

Date: _____

TO: ~~FILE NOTE~~

Location of site: <u>Pukuatua / Ranoff Strs</u>	JOB: Subdivision <u>Building / Development</u> Resource consent Other _____ (state)	Trade Waste Contaminant Litter / Refuse Fill _____ (circle as appropriate)
Weather: <u>Fine</u> Overcast Showers Raining (Circle as appropriate)	Photographs taken: yes / no Location of photograph: _____ Sample(s) taken: yes / no Type: _____	I.D. No: _____
Time of arrival: <u>4:15</u> Duration of visit: <u>10 min</u>		

Person(s) spoken to: Developer PH: _____

Observations / Report:

Inspected stormwater connection into existing stormwater system.
Pipe protruding into existing pipe to be re-laid level with edge of pipe.

The following action is required to be taken:

As Above.

Such action must be completed on or before clearance. A reinspection will take place after that date.

Signature: Karl Cherry

Name: _____

Position: Resource Technician

Copy to: Consultant Contractor Owner Occupier File (circle as appropriate)

Delivered by: Mail Fax Hand Other _____ (state) (circle as appropriate)

ROTORUA
DISTRICT
COUNCIL

Private Bag RO 3029
Rotorua
Telephone 07 3484199
Fax 07 3453143

INSPECTION NOTICE

0540
P00858

6500/744 P00854
728 P00857
729 P00855 *
731 P00856

File No. 657

Date: _____

TO: FILE NOTE

Location of site:

Pukaturu / Renoff Sts

JOB: Subdivision

Building / Development

Resource consent

Other _____ (state)

Trade Waste

Contaminant

Litter / Refuse

Fill _____ (circle as appropriate)

Weather:

Fine

Overcast

Showers

Raining

(Circle as appropriate)

Time of arrival: 4.15

Duration of visit: 10 min

Photographs taken:

yes / no

Location of photograph:

Sample(s) taken:

yes / no

Type:

I.D. No: _____

Person(s) spoken to: Developer

PH: _____

Observations / Report:

Inspected stormwater connection into
existing stormwater system.
Pipe protruding into existing pipe
to be re-laid level with edge of
pipe.

The following action is required to be taken:

As Above

Such action must be completed on or before clearance. A reinspection will take place after that date.

Signature: Karla Cheng

Name: _____

Position: Resource Technician

Copy to: Consultant Contractor Owner Occupier File _____ (circle as appropriate)

Delivered by: Mail Fax Hand Other _____ (state) _____ (circle as appropriate)