

Date 24.08.2023

Job # 14694

By John Frepaul.

Inspection # 01

Project

Lot 128
Westwood
Farnegdon

Constructure

Progress

Bearing check to waffle at
Contractor on site
BC 230719

Comments

Scale penetrometer tests.
results = 300 kpa ultimate bearing ~ grounds.

Actions

ok to proceed

Copies to

Joel / s teboa / Kevin