

07 May 2013



M S Bailey & T Liu
82 Chartwell Street
Burwood
Christchurch

Dear Sir or Madam,

Inspection Report

Reference Number: BC130229

Project Location: Lot 84 Dynes Road, Rolleston

Legal description of land where building is located: LOT 1500 DP 456110

Project Description: 3 Bedroom Domestic Dwelling with Study and Attached Garage - 201.99

Inspection Results: 07 May 2013

1ST INSPECTION

07 May 2013 @ 09:00 by Bruce Harris

Inspection Outcome: **PASS** - The BCA is satisfied, on reasonable grounds, that the aspects of building work pertaining to this inspection demonstrate compliance with the building consent.

All measurements to boundraies as per approved B/C.

Your next inspection will be: Prepour - Piles, Foundations, Slab

Please contact us 48 hours before you require this to book your inspection.

Site Inspection Summary / History To Date:

Inspection Name	Summary
1st Inspection	PASS - 07 May 2013
Prepour - Piles, Foundations, Slab	-
Subfloor - Drainage	-
Pre-wrap	-

Post Wrap	-
Half high Brick (211)	-
Preline Plumbing (205a)	-
Preline Building	-
Post Line	-
Drainage	-
Final	-

Yours Sincerely,

Bruce Harris

Contractor

On behalf of: Selwyn District Council