

10 May 2013



M S Bailey & T Liu
82 Chartwell Street
Burwood
Christchurch

Dear Sir or Madam,

Reference Number: BC130229

Project Location: Lot 84 Dynes Road, Rolleston

Legal description of land where building is located: LOT 1500 DP 456110

Project Description: 3 Bedroom Domestic Dwelling with Study and Attached Garage - 201.99

Inspection Results: 10 May 2013

SUBFLOOR - DRAINAGE

10 May 2013 @ 14:00 by Carl Greening

Inspection Outcome: **PASS** - The BCA is satisfied, on reasonable grounds, that the aspects of building work pertaining to this inspection demonstrate compliance with the building consent.

Your next inspection will be: Prepour - Piles, Foundations, Slab

Please contact us 48 hours before you require this to book your inspection.

Site Inspection Summary / History To Date:

Inspection Name	Summary
1st Inspection	PASS - 07 May 2013
Prepour - Piles, Foundations, Slab	-
Subfloor - Drainage	PASS - 10 May 2013
Pre-wrap	-
Post Wrap	-
Half high Brick (211)	-
Preline Plumbing (205a)	-
Preline Building	-

Post Line	-
Drainage	-
Final	-

Yours Sincerely,

Carl Greening
Building Control Officer
On behalf of: Selwyn District Council