

17 May 2013



M S Bailey & T Liu
82 Chartwell Street
Burwood
Christchurch

Dear Sir or Madam,

Reference Number: BC130229

Project Location: Lot 84 Dynes Road, Rolleston

Legal description of land where building is located: LOT 1500 DP 456110

Project Description: 3 Bedroom Domestic Dwelling with Study and Attached Garage - 201.99

Inspection Results: 17 May 2013

DRAINAGE

17 May 2013 @ 09:00 by Carl Petersen

Inspection Outcome: **PASS** - The BCA is satisfied, on reasonable grounds, that the aspects of building work pertaining to this inspection demonstrate compliance with the building consent.

The following matters were discussed on site with the Contractor and are required to be initiated prior to the next inspection -

Ensure to provide concrete protection to gulleys

Your next inspection will be: N/A

Please contact us 48 hours before you require this to book your inspection.

Site Inspection Summary / History To Date:

Inspection Name	Summary
1st Inspection	PASS - 07 May 2013
Prepour - Piles, Foundations, Slab	PASS - 13 May 2013

Subfloor - Drainage	PASS - 10 May 2013
Pre-wrap	-
Post Wrap	-
Half high Brick (211)	-
Preline Plumbing (205a)	-
Preline Building	-
Post Line	-
Drainage	PASS - 17 May 2013
Final	-

Yours Sincerely,

Carl Petersen
Building Control Officer
On behalf of: Selwyn District Council