

07 Jun 2013



M S Bailey & T Liu
82 Chartwell Street
Burwood
Christchurch

Dear Sir or Madam,

Reference Number: BC130229

Project Location: Lot 84 Dynes Road, Rolleston

Legal description of land where building is located: LOT 1500 DP 456110

Project Description: 3 Bedroom Domestic Dwelling with Study and Attached Garage - 201.99

Inspection Results: 07 Jun 2013

POST WRAP

07 Jun 2013 @ 15:00 by Bruce Harris

Inspection Outcome: **PASS** - The BCA is satisfied, on reasonable grounds, that the aspects of building work pertaining to this inspection demonstrate compliance with the building consent.

Ecoply system installed, fixings to requirements. Tapes over joins to be fitted.

Your next inspection will be: Half high Brick (211)

Please contact us 48 hours before you require this to book your inspection.

Site Inspection Summary / History To Date:

Inspection Name	Summary
1st Inspection	PASS - 07 May 2013
Prepour - Piles, Foundations, Slab	PASS - 05 Jun 2013
Wastepipes	PASS - 10 May 2013
Pre-wrap	PASS - 05 Jun 2013
Post Wrap	PASS - 07 Jun 2013

Half high Brick (211)	-
Preline Plumbing (205a)	-
Preline Building	-
Drainage	PASS - 17 May 2013
Final	-

Yours Sincerely,

Bruce Harris

Contractor

On behalf of: Selwyn District Council