

10 Taurus Place Street Lot 17 DPS 22220 Section Block

ROTORUA DISTRICT COUNCIL



BC

582

Plumbing to 2 Units

Owner: Nth Island Construction

Valuation No.: 654/891/31

Plumber: J.S. McHale

Permit No.: 582

Drainlayer:

Appn. No.: 10337

INSPECTIONS

Date: 6/11/79

DATE

26.6.80.

Plumbing inspection preflex pipe work on back unit. front unit complete but no cord on file. foundation of back unit laid in conjunction with front unit. drawings all completed in 1st stage of work.

29.7.80.

Plumbing inspection unit completely piped out.

9.2.81

Plumbing inspection unit complete

[Signature]

