



REG


HOUSE TO HOUSE INSPECTION

P16045

INFILTROL

Fault Diary

LOCAL AUTHORITY: ROTORUA DISTRICT COUNCIL FAULT NO. 84 502
ADDRESS: 14 Morey Street (22 Alastair ?) ENTRY: DOG/ACCESS



SKETCH PLAN

INSPECTION 8:2:94

FIELD OFFICER SROJ

Discussions? Onr/Fmy/Tnt/No

REINSPECTION (1) 16/5/94

FIELD OFFICER (B)

Discussions? Onr/Fmy/Tnt/No

REINSPECTION (2)

FIELD OFFICER

Discussions? Onr/Fmy/Tnt/No

NOTICE 10 MAR 1994

REMINDER 24 MAY 1994

FORMAL NOTICE

FINAL STATUS: NOT STD ☐ NOT CPT ☐ IN PGRS ☐

FAULTS: 1. Gully trap surround too low.

COMMENTS (incl. date):


MR/MRS/MS/MISS W. J. & C. M. MCKENNA

ADDRESS:

TELEPHONE

Home:

Work:



Private Bag RO 3029
Rotorua
New Zealand
Telephone 07-348 4199
Fax 07-346 3143

Address all
communications to:
District Manager
Rotorua District Council

24 May 1994

Please Quote:
P16045

WJ & CM McKenna
14 Morey Street
ROTORUA

Dear Sir/Madam

DRAINAGE REPAIR FINAL NOTICE: 14 Morey Street

You were requested to carry out the following drainage repairs by our drainage consultants, Infiltral, in a letter dated 10 March 1994 :

1. Gully trap surround too low.

A recent re-inspection revealed that the repairs had not been started.

You are reminded that the repair work is required in order to comply with the requirements of the Building Act 1991.

If you are uncertain about what is required, please telephone ⁽⁰⁴⁾ 347 2934 immediately and leave your name, address and telephone number with the receptionist.


The work must be finished for a final reinspection, by 24 June 1994.

If you have already completed the required work, we thank you for your co-operation and ask that you disregard this notice.

Yours faithfully

A G Borkus
INFILTRAL CONSULTANTS

*Complete
after it
27/6/94*



10 March 1994

WJ & CM McKenna
14 Morey Street
ROTORUA

Please Quote:
P16045

Private Bag RO 3029
Rotorua
New Zealand
Telephone 07-348 4199
Fax 07-346 3143

Address all
communications to:
District Manager
Rotorua District Council

Dear Sir/Madam

DRAINAGE REPAIR NOTICE: 14 Morey Street

Our drainage consultants, Infiltral, are doing a house-to-house drainage inspection in Rotorua for the District Council, and the following fault/s have been noted on the above property:

1. Gully trap surround too low.

As owners of the property, you are therefore requested to carry out the following repair work:

1. Install gully trap surround.

If you need assistance, it is suggested that you contact your plumber or drainlayer, but if there is any underground pipework involved you will require the services of a registered drainlayer in any case.

However you may be able to carry out this work yourself, and you are referred to the suggestions in the attached information pamphlet.

If you are uncertain about what is required, please telephone 347 2934 immediately and leave your name, address and telephone number with the receptionist.

The work you have been requested to do will help to reduce the frequency of sewer overflows in wet weather, and reduce the cost of operating the public sewer system.

This repair work on your drainage system is required in order to comply with the minimum legal standards for private drains, and so we look forward to your co-operation in this matter.

The work must be completed by 10 May 1994.

Yours faithfully

A G Borkus
INFILTROL CONSULTANTS




Fault Diary

LOCAL AUTHORITY: ROTORUA DISTRICT COUNCIL

FAULT NO. 84 502

ADDRESS: 14 Morey Street (22 Alastair ?) ENTRY: DOG/ACCESS



Install gully trap surround.

SKETCH PLAN

INSPECTION 8:2:94 FIELD OFFICER SROJ Discussions? Onr/Fmy/Tnt/No	REINSPECTION (1) FIELD OFFICER Discussions? Onr/Fmy/Tnt/No	REINSPECTION (2) FIELD OFFICER Discussions? Onr/Fmy/Tnt/No						
NOTICE 10 MAR 1994	REMINDER	FORMAL NOTICE FINAL STATUS: <table border="0"> <tr> <td>NOT STD</td> <td>NOT CPT</td> <td>IN PGRS</td> </tr> <tr> <td>☐</td> <td>☐</td> <td>☐</td> </tr> </table>	NOT STD	NOT CPT	IN PGRS	☐	☐	☐
NOT STD	NOT CPT	IN PGRS						
☐	☐	☐						
FAULTS: 1. Gully trap surround too low.								
COMMENTS (incl. date):								
MR/MRS/MS/MISS W.J. & C.M. MCKENNA								
ADDRESS:		TELEPHONE						
Home:		Work:						