

Property File:.....

Job history for Code Compliance Certificate No: 14902
as at Monday, 28 November 2016

Owner		Site Location				
Mark Russell O'Brien 26 Carlsberg Place Papamoa		10385 State Highway 2 South New lot 158 Papamoa Lot Pt lot 1 D.P. S 76448				
Job Description		Consent				
WorkType Dwelling - New IntendedUse Erect dwelling		Number 14902 Date Monday, 14 June 2004 Process Time 0. Hrs				
Inspection Summary						
	Required	Done	Passed	Failed	To Be Done	Extra Inspections 2
Building	6	7	7	0	0	
Plumbing/Drainage	4	5	4	1	0	
Structural	0	0	0	0	0	
Total	10	12	11	1	0	

Notes

Inspection Details

Date	Inspector	InspectionType	Result	Note
27/08/04	Mike Montgomery	Footing	Pass	
03/09/04	John Turner	Bond beam	Pass	
17/09/04	John Turner	Underfloor	Pass	Slab okay also.
19/10/04	Ian Watson	Plybracing	Pass	
01/12/04	Ian Watson	Preline/Building	Pass	
01/12/04	Ian Watson	Preline/Plumbing	Pass	
02/12/04	John Turner	Insulation	Pass	
09/12/04	John Turner	PreStopping	Pass	
16/12/04	John Turner	Drainage	Pass	Drain plan to receive.
19/05/05	John Turner	Final Plumbing	Fail	Laundry tub to be connected and fixed in place.
19/05/05	John Turner	Final Building	Pass	Producer statement required for tiled showers, electrical certificate. Received Producer Statement from Tilemaster (Pat Newson) for shower walls, bandaged waterproof membrane applied ABA superflex. Received Electrical Certificate of Compliance 25/5/05 dated 10/3/05.
24/05/05	John Turner	Final Plumbing	Pass	Laundry tub now connected and fixed in place. Drainage plan received 25/5/05.