

DETAILS			
Date: 17 / 10 / 18		Time: 0900	
Day: MON TUE <u>WED</u> THU FRI SAT SUN			
Person's present on property during issue of notice:		Yes ☐ No ☒	
Full Name Sandi Anderson			
Physical Address 108 Carbolino Rd, Mangauhai			
Telephone Number 021 257 5603			
CHECKLIST			
SEPTIC TANK		COMMENTS	
Inlet/outlet pipe in place	☒ Yes	No	Outlet pipe capped underground
Is there an effluent filter fitted?	Yes	☒ No	
Inlet/outlet pipe correct height	☒ Yes	No	
Outlet pipe restricted	Yes	☒ No	
Tank lid fitted	☒ Yes	No	400mm - 600mm underground
Mushroom in place	☒ Yes	No	
Access unobstructed	☒ Yes	No	
SOAKAGE FIELD			
Evidence of effluent run-off	Yes	No	
Excessive growth on soakage field	Yes	No	
GREASE TRAP			
Is there a grease trap fitted?	Yes	No	
Type of grease trap	Yes	No	
Is grease trap connected?	Yes	No	
ADDITIONAL DETAILS			
ADDITIONAL NOTES:			
Tank lid 400-800mm underground. Left exposed so owner can remedy with riser.			
Owner called & stated will do job.			
Septage removed: 4 m ³		Where was the septage disposed? Macjimray Treatment Plant	
Further investigation by Council required:		Yes ☐ No ☒	
Contractor's name: T. King		Signed: 	
Contractor's telephone number: 09 423 7014			
Bylaws can be viewed at Council offices and online at www.kaipara.govt.nz			