



Name: Looyenga Peter John

Address: 5 Redfern Lane (Pvt), MANDEVILLE NORTH


Tech 1 ID:	WW009727 - LOT 8 DP 328911
Task:	Check, clean, flush, disposal and report
Scope of Work:	Locate, de-sludge, flush and clean septic tanks/pump chamber, clean any biofilters, flush any stone filtration systems, measure the scum, supernatant and sludge, disposal to Bromley Sewer Treatment Plant. Note - tank and pump type, size of tank, any defects, stormwater, ingress, location of tank, and report any pump failure.

Reporting:	Yes	No	Comments
1. Tank – check, clean, flush	✓		
2. Pump chamber – check, clean, flush	✓		
3. Filters – check, clean	✓		
4. Post cleaning pump check	✓		
5. Reactivate tank	✓		
6. Stormwater ingress?	N		
7. Pre & Post Photo	✓		
8. Tank type	Oasis Z54 deluxe		
9. Tank capacity	4000L		
10. Pump type	Submersible		
11. Make/Model			
12. Any Defects			
13. Comments:			
PTO			

GPS Coordinates

East 0622699 **100**

North 5196454 **10**



0
measurements
in millimetres
10

GPS Device Make and Model Samsung Galaxy Tab A running "Handy GPS" app

Comments:


Date: 17/02/20

Service Person: Mike Wilson Contractor: WasteCo NZ Ltd Time: 2:15



New session

--- Paused ---



UTM

WGS84

Easting

622699

Northing

5196454

Accuracy

+/- 6 m

Altitude

53 m

Speed, direction

0 km/h, ?

Odometer

225.802 km

Reset

Timer

19:34:02

