

Septic Tank Cleaning Field

Address: 5 Redfern Lane

Date: 23/02/2024

Contractor WasteCo NZ Ltd

Tank Cleaned? Yes

Filters Cleaned/ Checked? Yes

Latitude/Longitude: -43.374704000000001/172.514633

Tank Info

Type: oasis

Capacity: 3000l

Pump Info

Separate Pump Chamber? Yes

Pump Type: submerged

Stormwater Ingress? No

Sludge/ Scum

Scum Chamber 1 (mm): 3mm Sludge Chamber 1 (mm): 1mm

Scum Chamber 2 (mm): 2mm Sludge Chamber 2 (mm): 1mm

Defects?

Comments:

23/02/2024 12:29:56

5 Redfern Lane, Mandeville North, , Mandeville



23/02/2024 11:53:47

5 Redfern Lane, Mandeville North, , Mandeville



23/02/2024 11:58:16

5 Redfern Lane, Mandeville North, , Mandeville



23/02/2024 11:52:13

5 Redfern Lane, Mandeville North, , Mandeville



23/02/2024 11:52:49

5 Redfern Lane, Mandeville North, , Mandeville



23/02/2024 12:34:13

5 Redfern Lane, Mandeville North, , Mandeville



23/02/2024 11:53:38

5 Redfern Lane, Mandeville North, , Mandeville

