

18 February 2020

J Singh & I Kaur
5 Brookside Terrace
Bryndwr
Christchurch 8053

Dear Sir or Madam,

Reference Number: BC192253

Project Location: 43 Nicolau Avenue
Rolleston

Legal Description: LOT 33 DP 535457

Project Description: 4 bedroom domestic dwelling with attached garage

IR Number: 2

Inspection Results:

FLOOR SLAB - 18 Feb 2020 @ 14:19 by Ian Buckle

Inspection Outcome: **PASS** - The BCA is satisfied, on reasonable grounds, that the aspects of building work pertaining to this inspection demonstrate compliance with the building consent.

Site Communication: No inspection carried out. Document receipt only

Your next inspection will be: **Framing / Pre-wrap**

Please contact us 48 hours before you require this to book your inspection.

Please ensure all work for inspection is ready the day before. All re-inspections will incur an additional inspection fee.

Outstanding Required Documents for this Building

Framing / Pre-wrap

- Form 6a - LBP record of building work - Carpentry

History

Inspection Name

Wastepipes

Floor Slab

Framing / Pre-wrap

Summary

PASS - 14 Feb 2020

PASS - 18 Feb 2020

-

Post Wrap / Cavity	-
Half High Brick	-
Preline	-
Drainage	-
Final	-

Yours Sincerely,

Ian Buckle
Building Control Officer
On behalf of: Selwyn District Council