

Statement of Insulation (where installed)



House Address	184 Great North Rd, Glendene, Auckland		
Date of Installation	8 July 2019		
Ceiling Insulation	160mm	Ecoinsulation Glasswool/Brown	R3.6
	Depth (mm)	Brand/Colour	R-Value
	Full Ceiling ✓		Partial Ceiling
Underfloor Insulation Installed	110mm	Pinkbatt/Pink	R2.6
	Depth (mm)	Brand/Colour	R-Value
	Full Underfloor ✓		Partial Underfloor
Wall Insulation	Unknown as wall insulation deemed not accessible		
Installation Team Location	Eco Insulation - Auckland		

Snug Homes for Rentals – a service by

0800 400 ECO | ecoinsulation.co.nz



Note

This statement is based on the installation and records collected by Eco Insulation team members on the day of the assessment and installation. Insulation materials are not fixed and can be disturbed and or moved by other trades.

Maintenance of Insulation

Insulation when installed correctly needs to be maintained;

- Do not compress insulation by storing items on top
- Ensure other trades when accessing ceilings/underfloors return the insulation back to its loft and without gaps and clearances maintained
- If insulation gets wet or damp, replace with fresh insulation
- Try not to stand on or move insulation once in place
- Make sure your building is weathertight.

Insulation that is not maintained properly will void product and installation warranties.