



Oasis Clearwater
ENVIRONMENTAL SYSTEMS

FIELD SERVICE REPORT
RESIDENTIAL & COMMERCIAL
WASTEWATER TREATMENT SYSTEMS

Date 20/11/24 Time 1:00pm Serviceperson GARY Council Waimak
Customer PAULA HUMPHREYS
Address 149 Hodgsons Road Loburn

SYSTEM TYPE Septic ☐ S2000 / SAF ☐ TEXASS ☐ MBR ☐ Other ☒
REASON FOR VISIT Service ☒ Call Out ☐ Commissioning ☐ Other ☐

Control Box / Electrical

Check Function	[<u>—</u>]
Air Pump	[<u>—</u>]
Air Filter Check & Clean	[<u>—</u>]
Alarm Light & Buzzer	[<u>—</u>]
Remote Alarm	[<u>N/A</u>]

Irrigation Pump Chamber / Tank

Pump(s) Check & Clean	[<u>✓</u>]
Alarm Float	[<u>—</u>]
Effluent Clarity	[<u>—</u>]
Chamber Clean & Desludge	[<u>—</u>]
Filter(s) Check & Clean	[<u>—</u>]

Primary Septic Chamber / Tank

Scum Layer	<u>20</u> cm
Biological Activity	[<u>—</u>]
Effluent Filter(s) Check & Clean	[<u>—</u>]
Desludging required	[<u>NO</u>]

General

Insect Infestation	[<u>✓</u>]
Odours	[<u>—</u>]
Flooding	[<u>—</u>]
Landscaping / Tank Access	[<u>—</u>]
Meter Reading	<u>N/A</u> m ³

Secondary Treatment Chamber / Tank

Sludge Build Up	[<u>—</u>]
Biomass Growth	[<u>—</u>]
Liquor Quality	[<u>—</u>]
Output Clarity	[<u>—</u>]
Sludge Return	[<u>—</u>]
Distribution Manifold	[<u>—</u>]
SAF/PBR/MBR Functioning	[<u>—</u>]
Blower Functioning	[<u>—</u>]
Pump(s) Clean & Check	[<u>N/A</u>]

Disposal Field

Dripper Functioning	[<u>✓</u>]
Flush Dripline	[<u>✓</u>]
Air / Vacuum Valves	[<u>—</u>]
Bark / Mulch / Soil Cover	[<u>—</u>]
Planting	[<u>—</u>]
Ponding / Bogging	[<u>—</u>]
Field Performance	[<u>Good</u>]
Exposed Tubing	[<u>—</u>]
Vehicle / Stock / Other Damage	[<u>—</u>]

NOTES SYSTEM SERVICED

MATERIALS USED	
Qty	Description
1	1 PISO AIR FILTER 80076930

Travel _____ kms Hours _____

NOTE: As part of Regional and/or Local Council consent compliancing of Onsite Wastewater Treatment Systems, servicing is required at the consented service interval. A copy of this form will be sent or made available to the appropriate consenting authorities.