

FIELD SERVICE REPORT

RESIDENTIAL & COMMERCIAL WASTEWATER TREATMENT SYSTEMS

Date 31/3/16 Time 1:45/3 Serviceperson Milce Council WDC
Customer McCaw
Address 424 Barkers Rd

SYSTEM TYPE Septic ☐ S2000 / SAF ☒ TEXASS ☐ MBR ☐ Other ☐

REASON FOR VISIT Service ☐ Call Out ☒ Commissioning ☐ Other ☐

Control Box / Electrical

Check Function	[<input checked="" type="checkbox"/>]
Air Pump	[<input checked="" type="checkbox"/>]
Air Filter Check & Clean	[]
Alarm Light & Buzzer	[]
Remote Alarm	[]

Irrigation Pump Chamber / Tank

Pump(s) Check & Clean	[<input checked="" type="checkbox"/>]
Alarm Float	[]
Effluent Clarity	[]
Chamber Clean & Desludge	[]
Filter(s) Check & Clean	[<input checked="" type="checkbox"/>]

Primary Septic Chamber / Tank

Scum Layer	<u>Flooded</u>	cm
Biological Activity	[]	
Effluent Filter(s) Check & Clean	<u>Blocked</u>	
Desludging required	[]	

General

Insect Infestation	[]
Odours	[<input checked="" type="checkbox"/>]
Flooding	[<input checked="" type="checkbox"/>]
Landscaping / Tank Access	[<input checked="" type="checkbox"/>]
Meter Reading	<u>good</u> m ³

Secondary Treatment Chamber / Tank

Sludge Build Up	[]
Biomass Growth	[]
Liquor Quality	[]
Output Clarity	[]
Sludge Return	[]
Distribution Manifold	[]
SAF/PBR/MBR Functioning	[]
Blower Functioning	[]
Pump(s) Clean & Check	[]

Disposal Field

Dripper Functioning	[]
Flush Dripline	[]
Air / Vacuum Valves	[]
Bark / Mulch / Soil Cover	[]
Planting	[]
Ponding / Bogging	[]
Field Performance	[]
Exposed Tubing	[]
Vehicle / Stock / Other Damage	[]

NOTES

Zobel filter fully blocked
& well backed up into
the primary chamber.
Pumped system down to
correct levels & serviced
Zobel filter etc.

Thanks, Milce

MATERIALS USED

Qty	Description

Travel kms Hours 1 1/4