

Vehicle Crossing Permit - VC220418

Property Owner Details		Contractor Details	
Name:	Wendelborn Property Limited	Business Name:	I Pave Concrete & Asphalt Limited
Property Address:	38 Crossley Avenue WOODEND	Postal Address:	PO Box 26067 North Avon Christchurch 8148
Phone Number:	0274310635	Phone Number:	0274352386
Email:	Info@wendelbornproperty.co.nz	Email:	ipave@xtra.co.nz

Agent Details		Property of Proposed Vehicle Entry	
Business Name:	SHC Limited	Street Name and Number:	38 Crossley Avenue
Postal Address:	PO Box 16499 Hornby Christchurch 8441	Town Area:	WOODEND
Contact Name:		Legal Description:	LOT 755 DP 582033 0.040200 Ha
Phone Number:	0272550633		
Email:	Olivia.Gallop@stonewood.co.nz		

Location Distances							
Distance to Left :	Nearest Boundary	6.397	Was Distance Correct?	Yes	Actual Distance:		Was Measurement Point Correct? Yes
Distance to Right:	Nearest Boundary	2.09	Was Distance Correct?	Yes	Actual Distance:		Was Measurement Point Correct? Yes
Width of Proposed Vehicle Driveway:		5	Was Distance Correct?	Yes	Actual Distance:		

Inspection

Location	
Compliant:	
Comments:	
Inspection History:	Last Inspn Comments: Must cut back to join on left side as can't have less than 1m between joins. SW outlet needs to be moved if within 1m of bottom ... Last Insptd By: Danika Turnbull Last Inspn Date: 14/02/2023 Last Compliance: Yes

Excavation	
Compliant:	
Comments:	
Inspection History:	Last Inspn Comments: The Excavation was not inspected as the property owner or agent did not request the required inspection prior to completion. The... Last Insptd By: Danika Sturges Last Inspn Date: 13/07/2023 Last Compliance: NotInspWAC

Compaction/Prepour	
Compliant:	
Comments:	
Inspection History:	Last Inspn Comments: Cleggs 15 to 24. Depth ok. Some river stones as per photos. Looks like spoil from another job. Meets compaction but not spec mat... Last Insptd By: Danika Sturges Last Inspn Date: 13/07/2023 Last Compliance: Yes

Final Inspection	
Compliant:	Yes
Comments:	
Inspection History:	

Photo 1:



Inspection Sign Off

Audited / Reviewed by:

Inspection Date: 12/10/2023

Inspection Time: 09:28 a.m.

A handwritten signature in black ink, appearing to read "Danika".

Inspector's name: Danika Sturges

Take 5 Form Completed: Yes

----- End of Report -----